



AVR128DA28/32/48/64

Silicon Errata and Data Sheet Clarification

The AVR128DA28/32/48/64 devices you have received conform functionally to the current device data sheet (<http://microchip.com/DS40002183>), except for the anomalies described in this document. The erratas described in this document will likely be addressed in future revisions of the AVR128DA28/32/48/64 devices.

Note:

- This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current.
- Refer to the Device/Revision ID section in the current device data sheet (<http://microchip.com/DS40002183>) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance.

Table of Contents

.....	1
1. Silicon Issue Summary.....	3
2. Silicon Errata Issues.....	4
2.1. Errata Details.....	4
2.2. EVSYS - Event System.....	4
2.3. PORT - I/O Pin Configuration.....	4
2.4. NVMCTRL - Nonvolatile Memory Controller.....	4
2.5. SPI - Serial Peripheral Interface.....	5
2.6. TCA - 16-bit Timer/Counter Type A.....	5
2.7. TWI - Two-Wire Interface.....	6
2.8. USART - Universal Synchronous and Asynchronous Receiver and Transmitter.....	6
3. Data Sheet Clarifications.....	7
4. Document Revision History.....	8
4.1. Revision History.....	8
The Microchip Website.....	9
Product Change Notification Service.....	9
Customer Support.....	9
Microchip Devices Code Protection Feature.....	9
Legal Notice.....	9
Trademarks.....	10
Quality Management System.....	10
Worldwide Sales and Service.....	11

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. A6 ^(*)	Rev. A7
EVSYS	2.2.1 The PB[7:6] and PE[7:4] Pins are Not Connected to the Event System	X	X
PORT	2.3.1 Digital Input on Pin Automatically Disabled When Pin Selected for Analog Input	X	X
NVMCTRL	2.4.1 Flash Mapping into Data Space Not Working Properly	X	X
SPI	2.5.1 SSD Bit Must Be Set When SPIROUTE Value = NONE	X	X
TCA	2.6.1 TCA1 Pinout Alternative 2 and 3 Not Functional	X	X
TWI	2.7.1 The Output Pin Override Does Not Function as Expected	X	X
	2.7.2 The 50 nS and 300 nS SDA Hold Time Selection Bits are Swapped.	X	X
USART	2.8.1 Open-Drain Mode Does Not Work When TXD is Configured as Output	X	X

Note:

(*) This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 EVSYS - Event System

2.2.1 The PB[7:6] and PE[7:4] Pins are Not Connected to the Event System

The PB[7:6] and PE[7:4] pins are not connected to the Event System. This is true for both input and output signals into the Event System on these pins.

Work around

None.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.3 PORT - I/O Pin Configuration

2.3.1 Digital Input on Pin Automatically Disabled When Pin Selected for Analog Input

If an input pin is selected to be analog input, the digital input function for those pins is automatically disabled.

Work around

None.


Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.4 NVMCTRL - Nonvolatile Memory Controller

2.4.1 Flash Mapping into Data Space Not Working Properly

The inter-section Flash protection mechanism does not take into account the FLMAP bit field in the NVMCTRL.CTRLB register when checking if the address is in BOOT, APPCODE or APPDATA sections. It uses for comparison only the address offset between Flash start address in data space (0x8000) and the accessed address. This will cause the mirroring of the BOOT section in each Flash section selected by FLMAP (in blocks of 32 KB). See image below:



BOOT area for devices without issue

BOOT area for devices with issue

For read operations, the FLMAP bit field works as documented when the Boot Read Protect (BOOTRP) bit is not enabled.

For write operations, the inter-section Flash protection works properly only when FLMAP is set to 0x00.

Work around

Use only store program memory (SPM) instructions to write and load program memory (LPM) instructions to read Flash memory.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.5 SPI - Serial Peripheral Interface

2.5.1 SSD Bit Must Be Set When SPIROUTE Value = NONE

When operating either SPIn module, when the PORTMUX.SPIROUTE selection is NONE, the \overline{SS} pin must be disabled (CTRLB.SSD = 1) to maintain Master mode operation.

Work around

None.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.6 TCA - 16-bit Timer/Counter Type A

2.6.1 TCA1 Pinout Alternative 2 and 3 Not Functional

It is not possible to configure TCA1 in PORTMUX.TCAROUTEA to use pinout alternative 2 and 3.

Work around

Use TCA1 pinout alternative 0 or 1.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.7 TWI - Two-Wire Interface**2.7.1 The Output Pin Override Does Not Function as Expected**

When TWI is enabled it overrides the output pin driver, but not the output value. So when the value in the port out (PORTx.OUT) register is '1', for the pins corresponding to the SDA or SCL, the output on the line will always be high.

Work around

Ensure that the value in the PORTx.OUT register corresponding to the SCL and SDA pins are '0' before enabling the TWI.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.7.2 The 50 nS and 300 nS SDA Hold Time Selection Bits are Swapped.

The bits corresponding to the SDA Hold Time (SDAHOLD) bit field in the TWIn.CTRLA register are swapped.

Work around

Use the 50 ns bit field selection for the 300 ns hold time and vice-versa.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

2.8 USART - Universal Synchronous and Asynchronous Receiver and Transmitter**2.8.1 Open-Drain Mode Does Not Work When TXD is Configured as Output**

When the USART TXD pin is configured as an output, it can drive the pin high regardless of whether the Open-Drain mode is enabled or not.

Work around

Configure the TXD pin as an input by writing the corresponding bit in PORTx.DIR to '0' when using Open-Drain mode.

Affected Silicon Revisions

Rev. A6	Rev. A7
X	X

3. Data Sheet Clarifications

None.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc Rev.	Date	Comments
A	04/2020	<ul style="list-style-type: none">Initial document release.

The Microchip Website

Microchip provides online support via our website at <http://www.microchip.com/>. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to <http://www.microchip.com/pcn> and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: <http://www.microchip.com/support>

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with

your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-5986-6

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit <http://www.microchip.com/quality>.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p>Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: http://www.microchip.com/support Web Address: http://www.microchip.com</p> <p>Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p>Austin, TX Tel: 512-257-3370</p> <p>Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p>Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p>Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p>Detroit Novi, MI Tel: 248-848-4000</p> <p>Houston, TX Tel: 281-894-5983</p> <p>Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p>Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p>Raleigh, NC Tel: 919-844-7510</p> <p>New York, NY Tel: 631-435-6000</p> <p>San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270</p> <p>Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078</p>	<p>Australia - Sydney Tel: 61-2-9868-6733</p> <p>China - Beijing Tel: 86-10-8569-7000</p> <p>China - Chengdu Tel: 86-28-8665-5511</p> <p>China - Chongqing Tel: 86-23-8980-9588</p> <p>China - Dongguan Tel: 86-769-8702-9880</p> <p>China - Guangzhou Tel: 86-20-8755-8029</p> <p>China - Hangzhou Tel: 86-571-8792-8115</p> <p>China - Hong Kong SAR Tel: 852-2943-5100</p> <p>China - Nanjing Tel: 86-25-8473-2460</p> <p>China - Qingdao Tel: 86-532-8502-7355</p> <p>China - Shanghai Tel: 86-21-3326-8000</p> <p>China - Shenyang Tel: 86-24-2334-2829</p> <p>China - Shenzhen Tel: 86-755-8864-2200</p> <p>China - Suzhou Tel: 86-186-6233-1526</p> <p>China - Wuhan Tel: 86-27-5980-5300</p> <p>China - Xian Tel: 86-29-8833-7252</p> <p>China - Xiamen Tel: 86-592-2388138</p> <p>China - Zhuhai Tel: 86-756-3210040</p>	<p>India - Bangalore Tel: 91-80-3090-4444</p> <p>India - New Delhi Tel: 91-11-4160-8631</p> <p>India - Pune Tel: 91-20-4121-0141</p> <p>Japan - Osaka Tel: 81-6-6152-7160</p> <p>Japan - Tokyo Tel: 81-3-6880-3770</p> <p>Korea - Daegu Tel: 82-53-744-4301</p> <p>Korea - Seoul Tel: 82-2-554-7200</p> <p>Malaysia - Kuala Lumpur Tel: 60-3-7651-7906</p> <p>Malaysia - Penang Tel: 60-4-227-8870</p> <p>Philippines - Manila Tel: 63-2-634-9065</p> <p>Singapore Tel: 65-6334-8870</p> <p>Taiwan - Hsin Chu Tel: 886-3-577-8366</p> <p>Taiwan - Kaohsiung Tel: 886-7-213-7830</p> <p>Taiwan - Taipei Tel: 886-2-2508-8600</p> <p>Thailand - Bangkok Tel: 66-2-694-1351</p> <p>Vietnam - Ho Chi Minh Tel: 84-28-5448-2100</p>	<p>Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p>Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p>Finland - Espoo Tel: 358-9-4520-820</p> <p>France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p>Germany - Garching Tel: 49-8931-9700</p> <p>Germany - Haan Tel: 49-2129-3766400</p> <p>Germany - Heilbronn Tel: 49-7131-72400</p> <p>Germany - Karlsruhe Tel: 49-721-625370</p> <p>Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p>Germany - Rosenheim Tel: 49-8031-354-560</p> <p>Israel - Ra'anana Tel: 972-9-744-7705</p> <p>Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p>Italy - Padova Tel: 39-049-7625286</p> <p>Netherlands - Druenen Tel: 31-416-690399 Fax: 31-416-690340</p> <p>Norway - Trondheim Tel: 47-72884388</p> <p>Poland - Warsaw Tel: 48-22-3325737</p> <p>Romania - Bucharest Tel: 40-21-407-87-50</p> <p>Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p>Sweden - Gothenberg Tel: 46-31-704-60-40</p> <p>Sweden - Stockholm Tel: 46-8-5090-4654</p> <p>UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>