

# TLE985x-Errata-100-Infineon

## TLE985xQX(W) Family

### Overview

This document lists the errata of the TLE985xQX(W) family.

It is strongly recommended that the device behavior and possible proposed workarounds are considered for the application.

### Referenced documents

**Table 1** Reference documents

Document type	Document reference	Issue date
Data Sheet	See Table 2	
User Manual	Infineon-TLE985xQX-UserManual-v01_00-EN.pdf	2019-12-10

### Affected products

**Table 2** List of affected products

Device	Reference datasheet	Issue date
TLE9850QX	Infineon-TLE9850QX-DataSheet-v01_00-EN.pdf	2019-07-26
TLE9851QXW	Infineon-TLE9851QXW-DataSheet-v01_01-EN.pdf	2020-03-23
TLE9852QX	Infineon-TLE9852QX-DataSheet-v01_00-EN.pdf	2019-07-26
TLE9853QX	Infineon-TLE9853QX-DataSheet-v01_00-EN.pdf	2019-07-26
TLE9854QX	Infineon-TLE9854QX-DataSheet-v01_00-EN.pdf	2019-07-26
TLE9854QXW	Infineon-TLE9854QXW-DataSheet-v01_01-EN.pdf	2020-03-23
TLE9855QX	Infineon-TLE9855QX-DS-DataSheet-v01_00-EN.pdf	2019-07-26

## Table of contents

	<b>Overview</b> .....	1
	<b>Table of contents</b> .....	2
<b>1</b>	<b>Product errata</b> .....	3
1.1	PLL loss of lock (0000052337-4) .....	3
1.1.1	Workaround .....	3
1.1.1.1	Bypass of PLL and fixed system frequency .....	3
1.1.1.2	Optional: Use of recovery routine .....	5
1.1.2	Design improvement .....	7
<b>2</b>	<b>Application hint</b> .....	8
2.1	ADC1 (HV-Channel) sampling switch activation .....	8
2.1.1	Workaround .....	8
	<b>Revision history</b> .....	9
	<b>Disclaimer</b> .....	10

Product errata

# 1 Product errata

This chapter lists the errata of the referenced products and documentation.

## 1.1 PLL loss of lock (0000052337-4)

### Behavior

The TLE985x provides a Phase-Locked-Loop (PLL) to generate the system frequency. Under certain conditions it may happen that the PLL issues a loss of lock. The probability for an erroneous PLL loss of lock to occur increases with higher temperature and longer operation times.

### Effects

In case of a PLL loss of lock, the system frequency will be switched to free running clock divided by K2, this might have the following effects to the application:

- System timing do not match anymore, e.g. LIN communication might not work properly, PWM period might be affected.
- WDT1 reset may occur.
- Digital filter times might not match anymore.

### 1.1.1 Workaround

#### 1.1.1.1 Bypass of PLL and fixed system frequency

As the source of the loss of lock detection is within the lock detection unit, a possible workaround is to bypass the PLL and use the internal oscillator (marked blue in [Figure 1](#)) as system frequency source only. This will lead to a fixed system frequency of 40 MHz.





Figure 1 Clock generation unit block diagram

Product errata

The switch to the internal oscillator will be done in the **System Control Register 0** by writing the bit field **SYSCLKSEL** to 11<sub>B</sub>:



**Figure 2** SCU\_SYSCON0

Due to the fact that this register is protected, it is required to open the register password protection. Please use the following example as reference:

**Change system clock source to f\_int**

```

001   SCU_OpenPASSWD();
002   SCU->SYSCON0.reg = (uint32)0xC0;
003   SCU_ClosePASSWD();

```

---

**Product errata**

**Excerpt from SCU.h**

```
001  /* Global Macro Definitions */
002  /**\brief  PASSWD Phrases, PASSWD Opened */
003  #define PASSWD_Open (0x98U)
004
005  /**\brief  PASSWD Phrases, PASSWD Closed */
006  #define PASSWD_Close (0xA8U)
007
008  /* How to open the password protection*/
009  INLINE void SCU_OpenPASSWD(void)
010  {
011      Field_Wrt32all(&SCU->PASSWD.reg, (uint8)PASSWD_Open);
012  }
013
014  /* How to close the password protection*/
015  INLINE void SCU_ClosePASSWD(void)
016  {
017      Field_Wrt32all(&SCU->PASSWD.reg, (uint8)PASSWD_Close);
018  }
```

**Additional note**

In case of "Config Wizard" usage, please select  $f_{SYS}$  as 40 MHz as well, otherwise timings (watchdog trigger, GPT, CCU6, ...) do not match anymore. Ensure disabling the loss of lock NMI (default setting) as the PLL is not used anymore:

SCU-NMICON.bit.NMIPLL = 0;

Additionally, it is recommended to verify the EMC behavior in your application, especially if a system frequency change was done.

**1.1.1.2 Optional: Use of recovery routine**

In the general case of PLL loss of lock, user software can try to configure the clock system again by executing the following sequence:

1. If input clock source is from XTAL (fOSC from OSC\_HP), ensure the input frequency is above threshold by checking OSC\_CON.OSC2L.
2. The Prescaler Mode has to be selected (PLL\_CON.VCOBYP = 1)
3. If desired, (re-)configure the PLL divider settings.
4. Setting the restart lock detection bit PLL\_CON.RESLD = 1
5. Waiting until the PLL VCO part becomes locked (PLL\_CON.LOCK = 1)
6. When the LOCK is set again, the Prescaler Mode can be deselected (PLL\_CON.VCOBYP = 0) and normal PLL operation is resumed.
7. Clear the PLL loss of lock NMI flag FNMIPLL.

---

**Product errata**

**PLL loss of lock recovery routine**

```
001  #include "tle985x.h"
002
003  /**\brief  PASSWD Phrases, PASSWD Opened */
004  #define PASSWD_Open (0x98U)
005  /**\brief  PASSWD Phrases, PASSWD Closed */
006  #define PASSWD_Close (0xA8U)
007
008  /* procedure to recover PLL as described in TLE985x User
009     Manual, Chapter 7.3.3.8 */
010  void SCU_RecoverPllLossOfLock(void)
011  {
012     /* variable to store/modify PLL_CON register */
013     uint32 pll_con = SCU->PLL_CON.reg;
014
015     /* set VCOBYP bit and UNPROT_VCOBYP bit */
016     pll_con |= (uint32)(1u << 3u);
017     pll_con |= (uint32)(1u << 19u);
018
019     /* Select Prescaler mode to Bypass PLL */
020     SCU->PASSWD.reg = PASSWD_Open;
021     SCU->PLL_CON.reg = pll_con;
022     SCU->PASSWD.reg = PASSWD_Close;
023
024     /* Restart Lock detection */
025     SCU->PLL_CON.bit.RESLD = 1u;
026
027     /* wait until PLL is locked */
028     /* In case PLL doesn't lock a WDT1 reset is performed */
029     while(SCU->PLL_CON.bit.LOCK != 1){}
030
031     pll_con = SCU->PLL_CON.reg;
032
033     /* clear VCOBYP bit and set UNPROT_VCOBYP bit */
034     pll_con &= ~(uint32)(1u << 3u);
035     pll_con |= (uint32)(1u << 19u);
036
037     /* Set PLL Normal mode */
038     SCU->PASSWD.reg = PASSWD_Open;
039     SCU->PLL_CON.reg = pll_con;
040     SCU->PASSWD.reg = PASSWD_Close;
041 }
```

In case the recovery routine is used, it is strictly recommended to validate the routine within the application use case.

---

**Product errata**

**1.1.2 Design improvement**

The next design release will be done by Q2 / 2021.

This release is fully software compliant to the existing version, so that it is not required to perform a re-qualification of the improved device.

Application hint

## 2 Application hint

### 2.1 ADC1 (HV-Channel) sampling switch activation

#### Behavior

Fast transients on an enabled ADC1 HV-Channel could activate the ADC sampling switch, which will lead to a load of 10 kΩ (+/- 20%) on the causing channel.

In case the corresponding channel will be selected (sequencer, etc.), the additional load will disappear again.

#### Effects for MONx pin

The activation will increase the input current (> 100 μA @  $V_S$  13.5 V) on the corresponding MONx pin. This increased current can cause a voltage drop across the external resistor. Depending on the value of the resistor, the voltage drop can be so high that a wrong low signal on the MONx will be detected.

#### 2.1.1 Workaround

To achieve robustness against ISO 7637-3 pulses, the recommended R-C filter from the Data Sheet is sufficient. To increase the robustness, an additional 10 nF capacitor ( $C_{1MONx}$ ) is recommended. This will lead to a C-R-C filter. See [Figure 3](#).




Figure 3 Application diagram example with C-R-C filters at MONx



---

**Revision history**

**Revision history**

<b>Revision</b>	<b>Date</b>	<b>Changes</b>
1.0	2020-07-24	Initial release

## Trademarks

All referenced product or service names and trademarks are the property of their respective owners.

**Edition 2020-07-24**

**Published by**

**Infineon Technologies AG**

**81726 Munich, Germany**

**© 2020 Infineon Technologies AG**

**All Rights Reserved.**

**Do you have a question about any aspect of this document?**

**Email: [erratum@infineon.com](mailto:erratum@infineon.com)**

**Document reference**

**IFX-wje1594363382351**

## IMPORTANT NOTICE

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

## WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.