

## Product Advisory


Issue Date: Feb 6, 2023

**Change Type:**

Resistor stuffing option on BOM PCBA

**Description and Extent of Change:**

The Link and Activity LEDs do not match the LED label marking on the bracket. The LED behavior is being swapped so the Link and Activity LEDs match the bracket labels. This update will enable bracket standardization across all SKU variants.



**Reasons for Change:**

Ensure LED Link and Activity match bracket labeling.

**Parts Affected:**

BRCM Part Number	New Revision Number
BCM957508-P2100G	28

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

LED behavior will match bracket labeling.

**Effective Date of Change:**

This will be implemented as running change starting after February 10, 2023.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.