

Product Advisory

Issue Date: August 29, 2022

Change Type:

Cage placement process update

Description of Change:

Changing from press-fit to soldered cages on Thor OCP 3.0 Ethernet NICs

Reason for Change:

Change being implemented to improve the retention force on connector

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, reliability and quality.

Effective Date of Change:

The BOM change will be implemented as a running change. Product shipments will begin after December 1, 2022.

Parts Affected:

BCM957502-N150FGB	BCM957504-N1100G
BCM957504-N1100FXB	BCM957504-N1100GI
BCM957504-N1100FYB	BCM957508-N2100G
BCM957504-N1100FZB	BCM957508-N2100L
BCM957504-N1100FY4Q	BCM957508-N2100LFRU
BCM957508-N1200FZ	
BCM957508-N1200FZQ	
BCM957502-N150G	

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.