

Product Advisory

Issue Date: February 7, 2020

Change Type:

Label related: Advisory regarding the RoHS status on the labels

Parts Affected:

See list of affected part numbers in the Appendix.


Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change to Fit, Form, Function, Quality, or Reliability due to this product advisory.

Description and Extent of Change:

Due to a change in the EU RoHS Directive exemption deadline, the RoHS status on the label will not accurately reflect the correct compliance information after February 29, 2020. The customer must convert to the RoHS compliant part number.

The typical location of the RoHS designation is indicated below.



RoHS designation status:

- March 1, 2020 and later: The label information is not valid.

Reasons for Change:

For these products, the exemption to RoHS compliance per the EU RoHS directive expires on February 29, 2020.

Effective Date of Change:

March 1, 2020



Appendix:

The affected part numbers are included in the table below.

Part Numbers	Part Numbers
BCM53019A1KFEBG	NL3360DFVH-266H
BCM53115SIPB	NL56617BFHV
BCM88025A0KF SBG	NL7128DFVH-266H
BCM88130B0KF SBG	NL7256DFVH-450H
NL101024EFH400CA3	NL7256DFVH-500H
NL101024EFH533HC03	NL7512DFVH-266
NL101024HFA575T3	NL7512DFVH-500HE
NL102048EFH533HCA3	XLP316LXD0800-22
NL102048HFA600T3	XLP308HXD1200-22
NL10512EFH400CA03	XLP308XD1200-22
NL10512EFH533HC03	XLP316HXD0900-22
NL71024HFGLC1400A	XLP316LXD1000-22
NL72048HFGLRC01400	XLP316LXD1200-22
NL72048HFGLRC01500	XLP316XD1200-22

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.