

PRODUCT CHANGE NOTIFICATION

Product Category FIBER PATCHCORDS 20221101-1

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 1-Nov-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Discontinuation of the OM3 and OM4 Non-Standard (FN) Colored Patch Cords replacements can use OM4+ Colored patch cords only.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	1	30

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Part	Discontinuation
		Date
FN2X2EPKLSBM002	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM005	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM010	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF015	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF050	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF080	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF110	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF140	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF170	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF200	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF240	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM004	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM009	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF005	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF020	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF060	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF090	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF120	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF150	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF180	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF220	NO-REPLACEMENT	30-Jan-23
FN1X2EPKLSCM002	NO-REPLACEMENT	30-Jan-23
FN1X2EPKLSCM003	NO-REPLACEMENT	30-Jan-23
FN1X2EPKLSCM005	NO-REPLACEMENT	30-Jan-23
FN1X2EPKLSCM010	NO-REPLACEMENT	30-Jan-23
FN1X2EPKLSKM003	NO-REPLACEMENT	30-Jan-23
FN1X2EPLLSKM001	NO-REPLACEMENT	30-Jan-23
FN1X2EPLLSKM002	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM003	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM004	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM007	NO-REPLACEMENT	30-Jan-23
FN2X2EPKLSBM008	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF005	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF010	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF020	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF030	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF060	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF075	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF090	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF100	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF120	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF130	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF150	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF160	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF180	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF190	NO-REPLACEMENT	30-Jan-23

FN2X2EPLLSBF220	NO-REPLACEMENT	30-Jan-23
FN2X2EPLLSBF230	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM002	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM003	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM005	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM008	NO-REPLACEMENT	30-Jan-23
FN3X2EPKLSDM010	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF001	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF010	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF015	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF030	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF050	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF075	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF080	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF100	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF110	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF130	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF140	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF160	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF170	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF190	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF200	NO-REPLACEMENT	30-Jan-23
FN3X2EPLLSCF230	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF005	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF010	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF015	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF020	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF030	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF050	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF060	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF075	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF080	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF090	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF100	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF110	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF120	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF130	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF140	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF150	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF160	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF170	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF180	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF190	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF200	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF220	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF230	NO-REPLACEMENT	30-Jan-23
FN4X2EPLLSDF240	NO-REPLACEMENT	30-Jan-23
FN6X2EPKLSFM004	NO-REPLACEMENT	30-Jan-23

FN1Z2EPKKSCM001	NO-REPLACEMENT	30-Jan-23
FN1Z2EPKLSCM001	NO-REPLACEMENT	30-Jan-23
FN1Z2EPLSSBM002	NO-REPLACEMENT	30-Jan-23
FN1Z2EPLSSBM1.5	NO-REPLACEMENT	30-Jan-23
FN2Z2EPKLNBM015	NO-REPLACEMENT	30-Jan-23