

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
M113F002S	MODEM M113M1/NB1 2GFB WORLDWIDE - LTE-M1 / NB-IOT BAND 12, 28, 13, 20, 26, 8, 3, 4, 25, 1 - 2G FB, RS-232 & USB PORTS - 2 I/OS - MPACK	C13	D13
M113F00FS	MODEM M113M1/NB1 WORLDWIDE - LTE-M1 / NB-IOT BAND 12, 28, 13, 20, 26, 8, 3, 4, 25, 1 - RS-232 & USB PORTS - 2 I/OS - MPACK	C13	D13

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved M-series M113 firmware version 2.4.0.0R1. The release includes new features and bug fixes including:

Bug fixes:

- 1) Data consisting '0x0D 0x0A' sent from TCP server to modem client gets corrupted.

Refer to the release notes for a complete list of features and bug fixes.

For customers that would like to take advantage of the new capabilities of firmware version 2.4.0.0R1, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

Reason for Change

New Firmware release

Effect of Change on Fit, Form, Function

Functional changes as noted on release notes.

Effective Date of Change

This change will go into effect for the listed products built from **August 16, 2022** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>