Customer Operations

Dear Valued NI Customer:
You are receiving this letter to keep you informed of changes to products that you have purchased in the past. This is being provided to you for consideration during future purchases of the same products. Detailed information on this change has been included below.

Affected Product Part Numbers

Assembly Part Number	Kit Part Number	Description
154939D-01L	154939-01	GPIB-USB-HS+ (BOARD ONLY)
183923L-01L	183923-01	PXI-GPIB BOARD ONLY
188513F-01L	188513-01	NI PCI-GPIB WITH NI-488.2 LICENSE, BOARD ONLY (TNT5004)
198405C-01L	198405-01	NI PCIE-GPIB WITH NI-488.2 LICENSE, BOARD ONLY
188513F-01L	778032-01	NI PCI-GPIB WITH NI-488.2
183923L-01L	778039-01	NI PXI-GPIB WITH NI-488.2
188513F-01L	778686-01	NI PCI-GPIB WITH NI-488.2 FOR LINUX
198405C-01L	778930-01	NI PCIE-GPIB WITH NI-488.2
191971D-01L	779732-01	GPIB-RS232 CONTROLLER & CONVERTER, U.S. 120VAC
191971D-01L	779732-04	GPIB-RS232 CONTROLLER & CONVERTER, UNIV EURO 240VAC
191971D-01L	779732-05	GPIB-RS232 CONTROLLER & CONVERTER, N. AMERICAN 240VAC
191971D-01L	779732-06	GPIB-RS232 CONTROLLER & CONVERTER, U.K. 240VAC
191971D-01L	779732-07	GPIB-RS232 CONTROLLER & CONVERTER, JAPAN 100VAC
191971D-01L	779732-09	GPIB-RS232 CONTROLLER AND CONVERTER WITH KOREAN POWER CORD (250V)
191971D-01L	779732-10	GPIB-RS232 CONTROLLER AND CONVERTER WITH CHINESE POWER CORD (250V)
191971D-01L	779732-11	GPIB-RS232 CONTROLLER AND CONVERTER, TAIWAN 125VAC
198405C-01L	779779-01	NI PCIE-GPIB, NI-488.2 FOR LINUX
198405C-02L	780575-01	NI PCIE-GPIB, LOW-PROFILE, WITH NI-488.2
190602A-02L	780936-01	NI PCIE-GPIB+, LOW-PROFILE, WITH NI-488.2
196541G-01L	781630-01	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, U.S. (120 VAC)
196541G-01L	781630-02	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, SWISS (220 VAC)
196541G-01L	781630-04	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, UNIV EURO (240 VAC)
196541G-01L	781630-05	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, N. AMERICA (240 VAC)
196541G-01L	781630-06	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, U.K. (240 VAC)
196541G-01L	781630-07	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, JAPAN (100 VAC)
196541G-01L	781630-09	GPIB-ENET/1000 WITH NI-488.2 FOR WINDOWS AND KOREAN POWER CORD (250V)
196541G-01L	781630-10	GPIB-ENET/1000 WITH NI-488.2 FOR WINDOWS AND CHINESE POWER CORD (250V)
196541G-01L	781630-11	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, TAIWAN (125 VAC)
196541G-01L	781630-12	GPIB-ENET/1000, NI-488.2 FOR WINDOWS, BRAZIL (250 VAC)
189140E-02L	781753-01	NI PXI-8232, GIGE AND GPIB CONTROLLER FOR WINDOWS AND LV RT
154939D-01L	783368-01	GPIB-USB-HS+, WITH NI-488.2 FOR WINDOWS
154939D-01L	783370-01	GPIB-USB-HS+, WITH NI-488.2 FOR MAC
147564B-01L	787723-01	GPIB-140B

Change Description

The manufacture of the products presented in the table above is currently undertaken by NI in Debrecen, Hungary. Going forward, these products will be manufactured by NI in Penang, Malaysia.

Impact

The scope of impact is limited to the geographic location in which the product is manufactured. The manufacturing location change has no impact on the form, fit, function or safety of the product(s).

Recommended Action

You are being notified of this change to help inform your future purchases of the above products. No further action is required on your part.

Contact Information

Please do not reply to this email. Should you need assistance, call the NI Customer Service Center (+1-(877)-388-1952), contact your local sales representative or contact us online.

Release Date

This change is effective 12/13/2022

If you are not the end user of this product(s), we request that you forward this notice to the end user or provide NI with information to help locate the end user.

Thank you for being an NI customer. We apologize for this inconvenience. We are committed to providing products and services that exceed customer expectations and maintaining your confidence in our products.