This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:
Obsolescence of Selected ADV7680 & ADV7682 Non-HDCP Models.

Publication Date: 18-Jun-2018

Last Time Buy Date: 13-Jun-2018

Last Time Ship Date: 20-Jun-2018

Revision Description:
Shorter LTB & LTS Dates

Reason For Discontinuance

We have recently reviewed our portfolio of products based on run rates.
This review has resulted in the discontinuance of these parts.

Comments

Please note that while the replacement parts are Pin for Pin, they do have customer license requirements for support by Analog Devices.

Supporting Documents   None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive			
Americas: PDN_Americas@analog.com	**Europe:** PDN_Europe@analog.com	**Japan:**	PDN_Japan@analog.com
		Rest of Asia:	PDN_ROA@analog.com

PDN 18_0028 Discontinued Parts Material List				
Model	**Product Family**	**Replacement Part**	**Pin To Pin Compatible**	**Comments**
ADV7680WBCPZ-P	ADV7680	ADV7680WBCPZ	Yes	Replacement Part requires customer to be both HDCP Licensee & HDMi Adopter
ADV7680WBCPZ-P-RL	ADV7680	ADV7680WBCPZ-RL	Yes	Replacement Part requires customer to be both HDCP Licensee & HDMi Adopter
ADV7682WBSWZ-P	ADV7682	ADV7682WBSWZ	Yes	Replacement Part requires customer to be both HDCP Licensee & HDMi Adopter
ADV7682WBSWZ-P-RL	ADV7682	ADV7682WBSWZ-RL	Yes	Replacement Part requires customer to be both HDCP Licensee & HDMi Adopter

Appendix A - PDN 18_0028 Revision History		
Rev	**Publish Date**	**Rev Description**
Rev. -	18-Jun-2018	Shorter LTB & LTS Dates