

Attn.: _____

HIROSE ELECTRIC CO., LTD.
5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

Product Change Notification

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below.

We request that you kindly offer your consent to this matter.

1	Products affected	Please refer to the attachment.
2	Replacement products	Please refer to the attachment.
3	Classification of change	For discontinued sales
4	Reason for change	For difficulty in replacing material used in product for 4 kinds of regulated phthalic acid.
5	Date of final reception of orders for the current product	October 31, 2018
6	Date of final shipment of the current product	June 30, 2019
7	Date of your acknowledgement	By March 31, 2018

We kindly request that you inform Hirose business representative of your acknowledgement by the aforesaid date.

In the absence of a response by this date, please be advised that replacement product that described above will be delivered.

If you should have any questions, please feel free to contact a Hirose business representative. Your understanding and cooperation are highly appreciated.

■ Product List Business430-17026_Discontinued Sales of RoHs2 (Restriction of 4 Phthalates) Non-Compliant Products

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
1	103-0292-5-71	SR30-10JM-6S(71)	103-0259-0-72	SR30-10JE-6S(72)
2	103-0295-3-71	SR30-10PA-6P(71)	103-0288-8-71	SR30-10PM-6P(71)
3	104-0423-8-71	HA16PRN-3SF-A(71)	104-0432-9-05	HA16PRM-3S(05)
4	104-0441-0-71	HA16PRN-3SE-A(71)	104-0421-2-71	HA16PRM-3SE(71)
5	109-1252-4-71	RM15WTP-CP(8)(71)		JR13WCC-8(**)
6	109-1254-0-71	RM15WTP-CP(10)(71)		JR13WCC-10(**)
7	109-1295-7-76	RM15WTPA-8P-(9)(76)		RM15WTPZ-8P(**)
8	109-1362-2-81	RM15WTPH-4S-(10)(81)		RM15WTJZA-4S(**)
9	109-8093-0-72	RM15WTRO-8P110A1F(72)		RM15WTRO-8P(72)
10	110-0525-0-00	HR10A-7R-4SC(73)35A1F		HR10A-7R-4SC(73)
11	120-0403-0-73	H/MS3108B18-10S-D(73)		H/MS3108B18-10S-D-T(**)
12	704-0016-3-47	HSC-PH2-A2(47)		HSC-PH2-E Series ※Material of rubber folder : TPEE
13	710-0003-3-60	HMUAJ-P1-H2(60)		HMUA*-P0.9-H2(**) series ※Material of hood : TPEE
14	710-0003-3-61	HMUAJ-P1-H2(61)		HMUA*-P0.9-H3(**) series ※Material of hood : TPEE
15	710-0107-9-04	HMUA-FK-A1255(04)		HMUA-FK-A1255(01) ※Without boot
16	710-0099-2-04	HMUA-FK-A125(04)		
17	101-0011-1-72	HS12RC(72)		
18	101-0027-1-72	HS14RC(72)		
19	101-0109-4-72	HS21RC(72)		
20	101-0148-6-72	HS25RC(72)		
21	101-0174-6-72	HS28RC(72)		
22	101-0207-3-72	HS35RC(72)		
23	103-0379-1-72	SR36-9P-10P(871)(72)		
24	103-0382-6-74	SR36A-9P-10P(448)(74)		
25	104-0426-6-71	HA16PK-4S(71)		
26	104-0705-0-77	HA216J-4P(77)		
27	109-0990-0-71	RM15TR-C7(71)		
28	109-0990-0-72	RM15TR-C7(72)		
29	109-1141-3-71	RM12WBP-2S(71)		
30	109-1142-6-71	RM12WBP-3S(71)		
31	109-1143-9-71	RM12WBP-4S(71)		
32	109-1144-1-71	RM12WBP-5S(71)		
33	109-1145-4-81	RM12WBP-6S(81)		
34	109-1146-7-71	RM12WBP-2P(71)		
35	109-1147-0-71	RM12WBP-3P(71)		
36	109-1148-2-71	RM12WBP-4P(71)		
37	109-1149-5-71	RM12WBP-5P(71)		
38	109-1525-5-71	RM31WTR-40P(71)		
39	109-1526-8-71	RM31WTR-55P(71)		
40	109-1528-3-71	RM31WTR-55S(71)		
41	109-1571-2-71	RM31WTP-40S(71)		
42	109-1572-5-71	RM31WTP-55S(71)		
43	109-1574-0-71	RM31WTP-55P(71)		
44	109-2001-0-71	RM215TP-10PC(71)		
45	109-2002-2-71	RM215TPA-10PC(71)		
46	109-2011-3-73	RM215TJA-10SC(73)		
47	110-0039-1-71	KMC9BPG-4P(71)		
48	110-0070-1-71	KMC9BPM-4P(71)		
49	110-0710-1-73	HR10A-13PB-20PC(73)		
50	112-0125-4-71	HR12-10P8PS3000(71)		
51	112-0128-2-71	HR12-10P8PS350(71)		
52	112-1008-6-71	HR12-14LA20PSDL750(71)		
53	112-2507-1-71	HR212-10R-8SC50A1F(71)		
54	112-3311-5-71	HR12A-10LAP8PS5000(71)		
55	113-5183-4-71	RP34L-5LP-3SC(1000)B(71)		
56	113-5185-0-71	RP34L-5LP-3SC(2000)B(71)		
57	114-2150-5-71	JR16WP-3PC(71)		
58	114-2151-8-71	JR16WP-3SC(71)		
59	120-0421-1-73	H/MS3108B10SL-3S-C-T(73)		
60	120-0424-0-73	H/MS3108B24-10S-G-T(73)		
61	120-0701-8-73	H/MS3108B10SL-4S(73)		
62	120-0703-3-73	H/MS3108B10SL-3S(73)		
63	120-0713-7-73	H/MS3108B22-14S(73)		
64	120-0715-2-73	H/MS3108B22-22S(73)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
65	120-0801-2-73	H/MS3057-4A(73)		
66	120-0804-0-73	H/MS3057-16A(73)		
67	120-0809-4-73	H/MS3057-4A1(73)		
68	121-0025-0-75	HR21-26TPA-8S(75)		
69	121-0026-3-75	HR21-26TPA-6S(75)		
70	121-0031-3-75	HR21-26TPA-8P(75)		
71	121-0051-0-75	HR21-26TPA-C(75)		
72	121-0054-9-75	HR21-26TRA-C(75)		
73	122-0026-0-73	HR22-12WTPE-20S(73)		
74	124-0001-1-74	HR24-8DPRB-4SA(74)		
75	124-0003-7-77	HR24-8DPR-4S(77)		
76	124-0004-0-77	HR24-8DPRA-4S(77)		
77	124-0004-0-78	HR24-8DPRA-4S(78)		
78	124-0051-0-78	HR24-8APR-4S(78)		
79	124-0101-6-77	HR24-8DRA-4P(77)		
80	124-0102-9-77	HR24-9DRA-4S(77)		
81	124-0220-5-77	HR24-9DP4P5050A(77)		
82	124-0611-2-77	HR24-8DJ4P1050A(77)		
83	124-0889-9-77	HR24-8AJ4P2050A(77)		
84	124-1200-3-77	HR24A-8DP4S1000(77)		
85	124-1207-2-77	HR24A-9DP4P5000(77)		
86	125-0524-6-72	HR25-7TRC-8S(72)		
87	206-2106-7-51	MQ170-NK-7P-CV2(51)		
88	206-2443-7-00	MQ198B-10S-CV		
89	206-2443-7-01	MQ198B-10S-CV(01)		
90	206-2532-5-00	MQ198B-10S-CV1		
91	222-1010-3-50	TM10R-64PR6468A(50)		
92	222-2275-3-00	TM20P-66P		
93	222-3671-6-50	TM4RV-88-RS(50)		
94	222-3890-0-50	TM10P-88PP-TSDP1000B(50)		
95	222-4067-7-30	TM2RCV-M88-10P-1100A(30)		
96	222-4408-6-30	TM2RCV-M88-10P-490A(30)		
97	222-4442-4-00	TM8RV-J64-4S-64M		
98	222-4628-2-30	TM2RCV-M88-10P-120A(30)		
99	222-4640-8-30	TM2RCV-M88-10P-1200RS(30)		
100	222-4644-9-30	TM2RCV-M88-10P-580RS(30)		
101	222-4653-0-30	TM2RCV-M88-10P-780RS(30)		
102	222-4660-5-00	TM3P-64PP-OKB2177-1FC		
103	222-4663-3-00	TM3P-6444PP-OK4W1000		
104	222-4664-6-00	TM3P-64PP-OK4B1027UA		
105	222-4665-9-00	TM3P-64PP-OK4B5027U		
106	222-4666-1-00	TM3P-62PP-KK2I3000A		
107	222-4669-0-00	TM2RCV-M88-10P-680A		
108	222-4678-0-00	TM3P-6444PP-OK4W500		
109	222-4679-3-00	TM3P-6444PP-OK4W2000		
110	222-4688-4-00	TM3P-44P01-OK4W1300		
111	222-4696-2-00	TM3P-64PP-OK4W1500		
112	222-4697-5-00	TM2RCV-M88-TSDP1500		
113	230-1022-7-50	DX30A-68PP-80CV1(50)		
114	230-1344-3-50	DX30A-36PP-10016(50)		
115	230-1395-4-50	DX30A-20P-10002(50)		
116	230-1564-0-00	DX30M-26PP-300CV(A)		
117	230-1565-2-00	DX30M-26PP-100CV(B)		
118	234-3006-7-00	NX15P-TM8P-1500		
119	242-1004-5-30	ZX64-B-5S-1000-STDA(30)		
120	313-0228-0-41	TWT2-P-4(41)		
121	321-4090-0-00	PO5G-2P-15HF-AT6P2SC-900F		
122	321-4090-0-01	PO5G-2P-15F-AT6P2SC-900FP		
123	321-5046-4-01	PO5G-P.J-15HF-AS3P2-850FP		
124	539-0348-0-91	WT-00003(91)		
125	539-0357-1-91	WAT-00097(91)		
126	539-0371-2-91	WAT-00191(91)		
127	781-0890-1-00	WAEGT8ZGT8E-0890		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

Acknowledgement

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We acknowledge the aforementioned matter.

Customer's name: _____

Acknowledgement stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

Document Receipt

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We received the document concerning the above.

Customer's name: _____

Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.