

PRODUCT CHANGE NOTIFICATION

Product Category FIBER CONNECTORS 20230216-3

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 16-Feb-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

As the required data rates and performance benchmarks for secure networks increases, the Keyed LC offering often requires fusion-spliced pigtails rather than mechanically spliced connectors. As such, the Keyed LC OptiCam offering will now be fully discontinued since the performance of these connectors does not meet the demands of common secure network designs. Customers requiring Keyed LC in a field-terminable format should contact Panduit for Keyed LC pigtails for splicing into their network.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	5	17

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s) Compatibility Type

FLCSMCXABL	No Replacement
FLCSMCXBRD	No Replacement
FLCSMCXCGR	No Replacement
FLCSMCXDYL	No Replacement
FLCSMCXEOR	No Replacement
FLCSMCXFDB	No Replacement
FLCSMCXGVL	No Replacement
FLCSMC6ABL	No Replacement
FLCSMC6BRD	No Replacement
FLCSMC6CGR	No Replacement
FLCSMC6DYL	No Replacement
FLCSMC6EOR	No Replacement
FLCSMC6FDB	No Replacement
FLCSSCABL	No Replacement
FLCSSCBRD	No Replacement
FLCSSCDYL	No Replacement
FLCSSCFDB	No Replacement