



Product Change Notification

TE Connectivity

Product Change Notification: P-22-022461

PCN Date: 05-APR-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Self Adhesive Labels for marking wire and Cables

Description of Changes

Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

Reason for Changes:

Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1768017-4	NO			"E68266-000", "EB5070"			
441072-000	NO			"318-LM", "3-1198182-0"			
5-1768016-2	NO			"D20594-000", "BKM-23050-9"			
748428-000	NO			"319-LE", "8-1198156-4"			
9-1768016-5	NO			"A86017-000", "CSL-09333P-9"			
9-1768016-8	NO			"E93653-000", "EB1119"			
A27907-000	NO			"6-1200611-5", "CP-508254-5-X"			
A41129-000	NO			"1200612-5", "HM-762381-2.5-8A"			
C17270-000	NO			"9-1200608-6", "HW-762381-2.5-9"			
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
CC0110-000	NO			"HLX125YW2NEL60S", "3-1899112-7"			
D11430-000	NO			"7-1200608-9", "HW-095095-10-9"			
D71439-000	NO			"CP-254254-10-X", "6-1200605-1"			
E21596-000	NO			"4-1200604-1", "EP-101508-2.5-9"			
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			
E74120-000	NO			"CP-229064-10-X", "3-1200603-2"			
F96395-000	NO			"9-1201552-1", "HMM-508064-10-8A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1768017-4	NO			"E68266-000", "EB5070"			
441072-000	NO			"318-LM", "3-1198182-0"			
748428-000	NO			"319-LE", "8-1198156-4"			
9-1768016-5	NO			"A86017-000", "CSL-09333P-9"			
9-1768016-8	NO			"E93653-000", "EB1119"			
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1768017-4	NO			"E68266-000", "EB5070"			
441072-000	NO			"318-LM", "3-1198182-0"			
5-1768016-2	NO			"D20594-000", "BKM-23050-9"			
748428-000	NO			"319-LE", "8-1198156-4"			
9-1768016-5	NO			"A86017-000", "CSL-09333P-9"			
9-1768016-8	NO			"E93653-000", "EB1119"			
A27907-000	NO			"6-1200611-5", "CP-508254-5-X"			
A41129-000	NO			"1200612-5", "HM-762381-2.5-8A"			
C17270-000	NO			"9-1200608-6", "HW-762381-2.5-9"			
D11430-000	NO			"7-1200608-9", "HW-095095-10-9"			
D71439-000	NO			"CP-254254-10-X", "6-1200605-1"			
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			
E74120-000	NO			"CP-229064-10-X", "3-1200603-2"			
F96395-000	NO			"9-1201552-1", "HMM-508064-10-8A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1768017-4	NO			"E68266-000", "EB5070"			
441072-000	NO			"318-LM", "3-1198182-0"			
748428-000	NO			"319-LE", "8-1198156-4"			
A27907-000	NO			"6-1200611-5", "CP-508254-5-X"			
A41129-000	NO			"1200612-5", "HM-762381-2.5-8A"			
C17270-000	NO			"9-1200608-6", "HW-762381-2.5-9"			
D11430-000	NO			"7-1200608-9", "HW-095095-10-9"			
D71439-000	NO			"CP-254254-10-X", "6-1200605-1"			
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			
E74120-000	NO			"CP-229064-10-X", "3-1200603-2"			
F96395-000	NO			"9-1201552-1", "HMM-508064-10-8A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
C78178-000	NO			"5-1200608-9", "EP-101165-0.85-9"			
CC0110-000	NO			"HLX125YW2NEL60S", "3-1899112-7"			
E21596-000	NO			"4-1200604-1", "EP-101508-2.5-9"			
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
E42900-000	NO			"7-1201552-3", "HMM-762508-2.5-8A"			