



## Product Discontinuance Notice - PDN 14\_0060 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

### PDN Title:

Discontinuance of Select Models of ADSP-BF506F

**Publication Date:** 08-Aug-2014

**Last Time Buy Date:** 17-Dec-2014

**Last Time Ship Date:** 17-Mar-2015

### Reason For Discontinuance

Analog Devices is discontinuing these specific product models due to decreased customer demand.

### Comments

Suggested replacement products are pin & code compatible.

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

<b>Americas:</b> PDN_Americas@analog.com	<b>Europe:</b> PDN_Europe@analog.com	<b>Japan:</b> PDN_Japan@analog.com
		<b>Rest of Asia:</b> PDN_ROA@analog.com

### PDN 14\_0060 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADSP-BF506KSWZ-3F	ADSP-BF506F	ADSP-BF506BSWZ-3F	Yes	Replacement is higher operating temp range.
ADSP-BF506KSWZ-4F	ADSP-BF506F	ADSP-BF506BSWZ-4F	Yes	Replacement is higher operating temp range.

Appendix A - PDN 14\_0060 Revision History

Rev	Publish Date	Rev Description
Rev. -	08-Aug-2014	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:792 Layout Rev:2 Parent DocId:None