



infrastructure for a connected world

PRODUCT CHANGE NOTIFICATION

Product Category COPPER QUICKNET & HIGH SPEED **20191022-01**

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 20191022

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit has discontinued the Active SFP+ Direct Attach Copper Assemblies. We will still offer the Passive SFP+ Direct Attach Copper Assemblies.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

| SCHEDULE FOR CHANGE | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|----------------|---------------|-------------|
| New product sample availability date | | | |
| Old product discontinuation date* | 2019 | 11 | 15 |

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be

| IMPACTED PART NUMBER(s) | Replacement Parts |
|--------------------------------|--------------------------|
| PSF1AXA3.5MBUN | No Replacement |
| PSF1AXA3MBL | No Replacement |
| PSF1AXA3MBLN | No Replacement |
| PSF1AXA3MBU | No Replacement |
| PSF1AXA3MGR | No Replacement |
| PSF1AXA3MOR | No Replacement |
| PSF1AXA3MRD | No Replacement |
| PSF1AXA3MWH | No Replacement |
| PSF1AXA4.5MBUN | No Replacement |
| PSF1AXA4MBL | No Replacement |
| PSF1AXA4MBU | No Replacement |
| PSF1AXA4MBUN | No Replacement |
| PSF1AXA4MGR | No Replacement |
| PSF1AXA4MOR | No Replacement |
| PSF1AXA4MRD | No Replacement |
| PSF1AXA4MWH | No Replacement |
| PSF1AXA5MBL | No Replacement |
| PSF1AXA5MBU | No Replacement |
| PSF1AXA5MGR | No Replacement |
| PSF1AXA5MOR | No Replacement |
| PSF1AXA5MRD | No Replacement |
| PSF1AXA5MWH | No Replacement |
| PSF1AXD10MBL | No Replacement |
| PSF1AXD10MBU | No Replacement |
| PSF1AXD10MBUBN | No Replacement |
| PSF1AXD10MGR | No Replacement |
| PSF1AXD10MOR | No Replacement |
| PSF1AXD10MRD | No Replacement |
| PSF1AXD10MWH | No Replacement |
| PSF1AXD13.5MBLN | No Replacement |
| PSF1AXD6MBL | No Replacement |
| PSF1AXD6MBU | No Replacement |
| PSF1AXD6MGR | No Replacement |
| PSF1AXD6MOR | No Replacement |
| PSF1AXD6MRD | No Replacement |
| PSF1AXD6MWH | No Replacement |
| PSF1AXD7MBL | No Replacement |
| PSF1AXD7MBU | No Replacement |
| PSF1AXD7MBUBN | No Replacement |
| PSF1AXD7MBUL | No Replacement |
| PSF1AXD7MGR | No Replacement |
| PSF1AXD7MOR | No Replacement |
| PSF1AXD7MRD | No Replacement |
| PSF1AXD7MWH | No Replacement |
| PSF1AXD8MBL | No Replacement |
| PSF1AXD8MBU | No Replacement |

