




Product Change Notification (PCN)

PCN Number	506235	Date Issued	January 16, 2019
Reason for Change	Packaging Method/Quantity Changing		
Change Type Description	This letter is to inform you that the part(s) referenced in this notice will undergo packaging specification changes that may include new container sizes, quantities or changes to the label. No changes will be made to the product as a result of this change.		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	April 01, 2019		
Sample Availability Date (Changed Part)	April 01, 2019		
Planned Implementation Date	July 16, 2019		

Before Change

- Packaging specification change for SL 70058 Series



After Change

Overview

- Aligning MLQ/DU values to packaging specifications listed for 70058 series. Reeled terminals will have a MLQ/DU packing quantity of 60K pcs. Loose terminals will have a packing quantity of MLQ 60K pcs / DU 20K pcs.
- Product Impact
 - No impact to fit, form or function
- Part Number Impact
 - See attached Sheet
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:506235**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Material	Old MLQ = MDQ	Old DU	Old PPQ	New MLQ	New DU	New PPQ
16020069	60,000	20,000	20,000	60,000	60,000	20,000
700584069	60,000	20,000	20,000	60,000	60,000	20,000
16020082	60,000	20,000	20,000	60,000	60,000	20,000
16020083	60,000	20,000	20,000	60,000	60,000	20,000
16020074	60,000	20,000	20,000	60,000	60,000	20,000
16020085	60,000	20,000	20,000	60,000	60,000	20,000
16020086	60,000	20,000	20,000	60,000	60,000	20,000
700584086	60,000	20,000	20,000	60,000	60,000	20,000
16020087	60,000	20,000	20,000	60,000	60,000	20,000
16020088	60,000	20,000	20,000	60,000	60,000	20,000
700581086	60,000	20,000	20,000	60,000	60,000	20,000
700581084	60,000	20,000	20,000	60,000	60,000	20,000
700581069	60,000	20,000	20,000	60,000	60,000	20,000
700580143	60,000	20,000	20,000	60,000	60,000	20,000
700580139	60,000	20,000	20,000	60,000	60,000	20,000
700580131	60,000	20,000	20,000	60,000	60,000	20,000
700580088	60,000	20,000	20,000	60,000	60,000	20,000
700580087	60,000	20,000	20,000	60,000	60,000	20,000
700580086	60,000	20,000	20,000	60,000	60,000	20,000
700580085	60,000	20,000	20,000	60,000	60,000	20,000
700580084	60,000	20,000	20,000	60,000	60,000	20,000
700580083	60,000	20,000	20,000	60,000	60,000	20,000
700580082	60,000	20,000	20,000	60,000	60,000	20,000
700580074	60,000	20,000	20,000	60,000	60,000	20,000
700580069	60,000	20,000	20,000	60,000	60,000	20,000
700581102	60,000	60,000	60,000	60,000	20,000	10,000
700581099	60,000	60,000	60,000	60,000	20,000	10,000
700581096	60,000	60,000	60,000	60,000	20,000	10,000
700580147	60,000	60,000	60,000	60,000	20,000	10,000
700580144	60,000	60,000	60,000	60,000	20,000	10,000
700580140	60,000	60,000	60,000	60,000	20,000	10,000
700580104	60,000	60,000	60,000	60,000	20,000	10,000
700580103	60,000	60,000	60,000	60,000	20,000	10,000
700580102	60,000	60,000	60,000	60,000	20,000	10,000
700580101	60,000	60,000	60,000	60,000	20,000	10,000
700580100	60,000	60,000	60,000	60,000	20,000	10,000
700580099	60,000	60,000	60,000	60,000	20,000	10,000
700580098	60,000	60,000	60,000	60,000	20,000	10,000
700580097	60,000	60,000	60,000	60,000	20,000	10,000
700580096	60,000	60,000	60,000	60,000	20,000	10,000

Molex Part #

16020069

16020074

16020082

16020083

16020086

16020087

16020088

700580069

Part numbers affected:

16-02-0069
16-02-0082
16-02-0086
16-02-0087
16-02-0088
70058-0086