

Issue Date: March 31<sup>st</sup>, 2020  
By: Julio Sanchez  
Associate Product Manager  
jcsanchez@littelfuse.com

**Type of Notification: HBC product line – Sourcing Issue**

**Description:**

The orders for the following part numbers will be blocked due to tool worn out and low volume. Littelfuse won't be accepting orders.

**Product Affected:**

Part Description	Part Number
ACS 3AG FUSEHOLDER	03420001X
ACS 3AG FUSEHOLDER	03420001Z
ACS 3AG FUSEHOLDER	03420001H
ACS 3AG FUSEHOLDER BODY ASSY	03420001ZX010
BODY S/A	342001-010

Please contact your local LF sales person with any questions or requests.