



PCN - 11 097

Issue Date: October 27 2011

Product Name:	PC Contact			
	PV Contact			
Product Manager:	Franck CHAPOUILLY			
Subject:	Product Change Notification			
Distribution:	Global			
Type of Change:	Product Design Change			
Change Description:	Removes gold flash only from the inside of the Insulation Crimp barrel & the pilot hole carrier feed strip. Gold flash remains inside the wire barrel & interior of the terminal box that houses the spring.			
Reason for Change:	To avoid price increases since FCI and its customers continue to be vulnerable to market fluctuations and price increase on the precious metals used in electronic connectors. Connectors will continue to meet the performance characteristics documented in the product specification			
Affected Parts:	See list attached			
Effective Date of Change:	January	01	2012	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	No			
Qual/Test Data Attached?	No			
Samples Availability Date:	N/A	N/A	N/A	
Available Alternatives?	No			
Questions?	Franck CHAPOUILLY Product Manager Ph: + 3 33 81 54 59 86 franck.chapouilly@fciconnect.com			