

Information note

N° 001/23

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Wire sweep improvement for product TLF80511TC_GRN

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Herbert Diess

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 001/23

► **Products affected**

Please refer to attached affected product list
“INF_001_23_[customer-no].pdf”


► **Detailed change information**

Subject Wire sweep improvement for product TLF80511TC_GRN.


Reason Improvement of wire sweep by modifying the die placement position.

Description

Old



New



► **Product identification**

Not applicable (no change of product).

► **Impact of change**

Based on the assessment of the qualification results, Infineon does not expect any negative impact on function, quality and reliability.

► **Attachments**

INF_001_23_[customer-no].pdf

affected product list

► **Intended start of delivery**

2023-03-31

If you have any questions, please do not hesitate to contact your local sales office.

INF 001/23



Wire sweep improvement for product TLF80511TC_GRN

Affected products sold to DIGI-KEY (4002348)

| Sales name | SP number | OPN | Package | Customer part number |
|------------|-------------|-----------------|--------------|----------------------|
| TLF80511TC | SP000906390 | TLF80511TCATMA1 | PG-TO263-3-1 | TLF80511TCATMA1 |
| TLF80511TC | SP001602622 | TLF80511TCATMA2 | PG-TO263-3-1 | TLF80511TCATMA2 |