



# Product Change Notification (PCN)

PCN Number	506204	Date Issued	November 27, 2018
Reason for Change	Equipment Transfer, Production Transfer or Rearrangement		
Change Type Description	This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	February 28, 2019		
Sample Availability Date (Changed Part)	February 28, 2019		
Planned Implementation Date	May 27, 2019		
Method of Identifying Change	Product made after planned implementation date can contain the change		

## Before Change

- Wire Pin Terminal (Metal Only)



1 Molex Confidential Information  
© 2018 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



## After Change

### Overview

- New tooling for wire pins to be manufactured out of St. Petersburg, FL plant. These are currently being made in Taiwan
- .Product line
  - KRIMPTITE WIRE PINS 22 - 10 AWG
- Product Impact
  - "no impact to fit, form or function"
- .Part number Impact
  - See Attached List
- Qualification data upon request after implementation date.

2 Molex Confidential Information  
© 2018 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.





## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:506204**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

192110003

192110005

192120003

192120005

192130008

192130009

192130010

192130011

192130012

**Part numbers affected:**

19212-0001
19212-0003
19212-0005
19213-0007
19213-0011
19213-0012