

PRODUCT CHANGE NOTIFICATION (PCN)

Product Category CABLE ACCESSORIES 20210226-1

Product Group CABLE ACCESSORIES

ISSUE DATE: 20210226

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The tooling that is used to make part CSMS spacer was revised by adding additional knockout pins. The finished part reflects this change, going from one KO mark on each side (photo below, left) to two KO marks on each side (photo, right). Change was made for better processing and quality. This modification does not in any way affect fit or function to the part.



Before



After

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[CSMS-D71 - running change](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	3	1
Old product discontinuation date*			

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.