


Light is OSRAM

Product Discontinuation (acc. JEDEC J-STD-048) OS-PD-2017-059

9/15/2017

Last order:	3/15/2018
Last delivery:	9/15/2018
Reason:	Product streamline/discontinue



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Brand	Device	Datasheet Ordering Code	Function	Brand
GW SBLMA3.EM-HR-XX33-L1-65-R18-XX	Q65112A0903	LED	DURIS S 2	No replacement Q code			
GW SBLMA3.EM-HR-XX35-L1-65-R18-XX	Q65112A0902	LED	DURIS S 2	No replacement Q code			
GW SBLMA3.EM-HDHR-XX37-L1-65-R18-XX	Q65112A0906	LED	DURIS S 2	No replacement Q code			
GW SBLMA3.EM-HR-XX31-L1-65-R18-XX	Q65112A0907	LED	DURIS S 2	No replacement Q code			
GW SBLMA3.EM-HDHR-XX37-L1L2-65-R18-XX	Q65112A2003	LED	DURIS S 2	No replacement Q code			
GW SBLMA3.EM-HR-XX35-L1L2-65-R18-XX	Q65112A2002	LED	DURIS S 2	No replacement Q code			

Products Affected by Product Discontinuation Notification

Number: OS-PD-2017-059

Name: Discontinuation due to Product Offering Streamline

Release Date: 9/15/2017

Last Order: 3/15/2018

Last Delivery: 9/15/2018

DISCONTINUED

NEW (REPLACEMENT)

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>	<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
GW SBLMA3	Q65112A0902	GW SBLMA3.EM-HR-XX35-L1-65-R18-XX	GW SBLMA3.EM-HR-XX35-L1-XX	No replacem		No replacement Q code	
GW SBLMA3	Q65112A0903	GW SBLMA3.EM-HR-XX33-L1-65-R18-XX	GW SBLMA3.EM-HR-XX33-L1-XX	No replacem		No replacement Q code	
GW SBLMA3	Q65112A0906	GW SBLMA3.EM-HDHR-XX37-L1-65-R18-XX	GW SBLMA3.EM-HDHR-XX37-L1-XX	No replacem		No replacement Q code	
GW SBLMA3	Q65112A0907	GW SBLMA3.EM-HR-XX31-L1-65-R18-XX	GW SBLMA3.EM-HR-XX31-L1-XX	No replacem		No replacement Q code	
GW SBLMA3	Q65112A2002	GW SBLMA3.EM-HR-XX35-L1L2-65-R18-XX	GW SBLMA3.EM-HR-XX31-L1-XX	No replacem		No replacement Q code	
GW SBLMA3	Q65112A2003	GW SBLMA3.EM-HDHR-XX37-L1L2-65-R18-X	GW SBLMA3.EM-HDHR-XX37-L1L2-	No replacem		No replacement Q code	