



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 278088

2. Date of Announcement: August 05, 2016

3. Series:

- FHP - .156 HI POWER SOCKET ASSEMBLY

4. Part #'s Affected

- FHP-XX-XX-XX-S-XX-XX-XX

5. Description of Change:

Footprint updated to center tails on pads for surface mount FHP

6. Method of Identifying Change

PCBs with pads updated to match this footprint revision will have alignment pin holes offset from pad pattern by .009".

7. Reason for Change:

For customer to design PCB layout more effectively and to reduce confusion regarding tail-pad offset.

8. Impact of Change on Form, Fit, or Function:

- Fit - Tails will be centered on pads using this revision of footprint layout
- Form - Pad pattern centerline will be visibly offset from alignment pin pattern centerline.

9. Projected Implementation Date: September 04, 2016