



ESSENTRA

COMPONENTS

February 1, 2021

To whom it may concern:

This is to inform you that Essentra has made the decision to obsolete the following part numbers. Our tooling for this part is not sufficient. There is no replacement part. This goes into effect immediately

SWI1640A
SWI1690A
SWI1880A
SWI1930A
SWI1960A

Please let me know if you have any questions.

Best Regards,

Greg P. Mifsud
Director of Product Management

ESSENTRA COMPONENTS
3123 Station Road
Eric, PA 16510
United States of America

T (800) 899-9440
F (814) 899-2586
E saleserie@essentracomponents.com
www.essentracomponents.com