

TE Connectivity

Product Change Notification: E-20-007238 PCN Date: 26-MAY-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Replacement anvil P/N 606106-1 and replacement blade P/N 606105-1 for ribbon cable cutting tool.

Description of Changes

Part numbers 606106-1 and 606105-1 are being obsoleted due to the manufacturer no longer manufacturing the parts.

Reason for Changes:						
Discontinuance. Parts are unavailable.						
Estimated Dates:						
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):	First Date To Ship (Changed Parts Only):				
29-MAY-2020						
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
05-JUN-2020	No Mixed Shipments					

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>606105-1</u>	YES						
606106-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
606105-1	YES						
606106-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
606105-1	YES						
606106-1	YES						