

**Part Change Notification Number:**  
TGEANA\_PCN\_0069

[sales@tglobaltechnology.com](mailto:sales@tglobaltechnology.com)

t: +44 (0)1455 553 510

**Date:** 19<sup>th</sup> April 2022

**Parts Affected:** TG-T1000

Old Manufacturer Part Number	Old Digikey Part Number	Replacement Manufacturer Part Number	Replacement Digikey Part Number
TG-T1000-325-325-0.5	1168-TG-T1000-325-325-0.5-ND	TG-T1000-325-325-0.25	1168-TG-T1000-325-325-0.25-ND

**Reason:** Wrinkled Sheets

**Description:** T-Global are obsoleting the part TG-T1000-325-325-0.5 due to an ongoing problem with wrinkled and defective sheets. The advised replacement part is TG-T1000-325-325-0.25 which is the same material but in a 0.25mm thickness instead of 0.5mm. For further information, please contact [sales@tglobaltechnology.com](mailto:sales@tglobaltechnology.com).

**Last Buy:** Effective immediately



**Approved By:** Duncan Bell, General Manager