

# PRODUCT CHANGE NOTIFICATION

Product Category SURFACE RACEWAY **20230224-1**

Product Group ROAR

ISSUE DATE: 24-Feb-23

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

## DESCRIPTION OF CHANGE: (Required)

Panduit will be making the following changes, effective throughout all territories and countries in the EMEA (Europe, Middle East, Africa) and APAC (Asia Pacific) markets only. The Above Floor Raceway product line will no longer be a part of our standard product offering in the EMEA and APAC regions effective May 25th, 2023.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

## DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	5	25

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

## CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	CHINA: 400-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA 1800 801435 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customerService@panduit.com">MEX-customerService@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
NORTH AMERICA	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	EMEA FORM C2-1003 DATE: 06 APR 21 APPR. MURILLO	EMEA: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

**IMPACTED PART NUMBER(s)**

AFR4BCBL6

AFR4BCOS6

AFR4CCBL

AFR4CCOS

AFR4ECBL

AFR4ECOS

AFR4JB2SBL

AFR4JB2SOS

AFR4RABL

AFR4RAOS

AFR4SAM18IN

AFR4TBLGBL

AFR4TBLGOS

AFR4TRT70BL

AFR4TRT70OS

AFR4WTRBL

AFR4WTROS