



PRODUCT DISCONTINUATION NOTICE

PDN No.: USA2013/003

IXYS PRODUCT TYPE:	TYPE:	RECOMMEND REPLACEMENT:				
SPECIAL PART NUMBER (SPN)	TO220PS & TO220PS HV	NO RECOMMENDATION				
<u>POLAR HIPERFETS</u>						
IXFV96N15PS	IXFV74N20PS	IXFV22N50PS	IXFV26N50PS	IXFV30N50PS	IXFV18N60PS	IXFV22N60PS
IXFV26N60PS	IXFV30N60PS	IXFV12N80PS	IXFV14N80PS	IXFV20N80PS	IXFV18N90PS	IXFV10N100PS
IXFV12N100PS	IXFV15N100PS					
<u>POLAR STANDARD MOSFETS</u>						
IXTV26N50PS	IXTV30N50PS	IXTV36N50PS	IXTV18N60PS	IXTV22N60PS	IXTV26N60PS	IXTV30N60PS
<u>TRENCH HIPERFETS</u>						
IXFV110N25TS						
<u>TRENCH POWER MOSFETS</u>						
IXFV110N25TS IXTV200N10TS						

REASON FOR DISCONTINUATION: LACK OF DEMAND FOR THIS PRODUCT

LAST TIME ORDER DATE: DEC. 2013

LAST TIME DELIVERY DATE: DEC. 2014

INTERNAL REFERENCE: N/A

In case of any question, please contact

INITIATOR: GORDON ROSETE	TITLE/FUNCTION DEPT. HEAD QUALITY ASSURANCE	DATE FEB. 22, 2013	E-MAIL G.ROSETE@IXYS.NET
-----------------------------	---	-----------------------	-----------------------------

CUSTOMER RESPONSE: (FOR PDN # 2013/003)

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

for further questions/ information
please comment

Company: _____
Name & Position _____
Phone / Fax No: _____

COMMENTS: _____

