



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016790

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	16-JAN-2019

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006977P007	NO			"1-1190054-4", "FL2500-NO.0-17-0-65MM"			
074977-000	NO			"9-1190560-2", "V4-1/8-0-SP"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
1630834001	NO			"1-1191177-8", "CGPT-3/1-0-SP"			
240345J001	NO			"1-1191766-2", "V2-10.0-0-FSP-SM"			
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3421334005	NO			"3-1192579-5", "CGAT-6/2-0-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
389957J001	NO			"9-1192927-2", "V2-3.0-0-SP-SM"			
4036954002	NO			"4-1193047-7", "CGPT-1.5/0.5-0-SP"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
4613294001	NO			"3-1193460-0", "CGPT-3/1-9-SP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934055	NO			"2-1193826-6", "RNF-100-1/16-9-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053004011	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1-1193835-5", "RNF-100-1/8-2-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053094080	NO			"3-1193845-6", "RNF-100-1/4-0-SP", "RNF-100-1/4-0"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053154018	NO			"6-1193857-6", "RNF-100-3/8-2-SP"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5067134001	NO			"6-1193931-2", "CGPT-76/38-6-SP"			
5069834023	NO			"9-1193949-2", "CGPT-4.8/2.4-0-SP"			
5069994004	NO			"5-1193958-8", "CGPT-19/9.5-9-SP"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5260010007	NO			"3-1194133-8", "TC-CAPS-4001-9"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5522244003	NO			"8-1194364-4", "RNF-3000-6/2-8-SP"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677714002	NO			"7-1194501-4", "RNF-3000-6/2-4-SP"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P039	NO			"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6339874001	NO			"6-1195014-5", "CGPT-12/4-0-SP"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
663099J001	NO			"5-1195226-9", "V2-22.0-0-FSP-SM"			
6823354001	NO			"4-1195363-0", "CGPT-6/2-0-SP"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
757543J001	NO			"1195903-8", "V2-20.0-0-FSP-SM"			
779783J001	NO			"1196068-8", "V2-3.5-0-SP-SM"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
8862474002	NO			"NETM1000-6-0-SP", "1448803-1"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9251514001	NO			"1197176-8", "V4-3/8-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9856874001	NO			"7-1197614-1", "CGPT-12/4-9-SP"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5099-000	NO						
CB5105-000	NO						
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5370-000	NO						
CB5385-000	NO						
CF6155-000	NO						
CF6166-000	NO			"9-1191306-3"			
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-19-0-STK"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10114001	NO						
NB10594001	NO						
NB11234001	NO						
NB11382001	NO						
NB11644001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006977P007	NO			"1-1190054-4", "FL2500-NO.0-17-0-65MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
240345J001	NO			"1-1191766-2", "V2-10.0-0-FSP-SM"			
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
389957J001	NO			"9-1192927-2", "V2-3.0-0-SP-SM"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5260010007	NO			"3-1194133-8", "TC-CAPS-4001-9"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677714002	NO			"7-1194501-4", "RNF-3000-6/2-4-SP"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P039	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
757543J001	NO			"1195903-8", "V2-20.0-0-FSP-SM"			
779783J001	NO			"1196068-8", "V2-3.5-0-SP-SM"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5385-000	NO						
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006977P007	NO			"1-1190054-4", "FL2500-NO.0-17-0-65MM"			
074977-000	NO			"9-1190560-2", "V4-1/8-0-SP"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
240345J001	NO			"1-1191766-2", "V2-10.0-0-FSP-SM"			
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
389957J001	NO			"9-1192927-2", "V2-3.0-0-SP-SM"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5260010007	NO			"3-1194133-8", "TC-CAPS-4001-9"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5522244003	NO			"8-1194364-4", "RNF-3000-6/2-8-SP"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677714002	NO			"7-1194501-4", "RNF-3000-6/2-4-SP"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P039	NO			"4-1194804-6", "SCT-NO.2-E5-0-50MM"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6339874001	NO			"6-1195014-5", "CGPT-12/4-0-SP"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
663099J001	NO			"5-1195226-9", "V2-22.0-0-FSP-SM"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
757543J001	NO			"1195903-8", "V2-20.0-0-FSP-SM"			
779783J001	NO			"1196068-8", "V2-3.5-0-SP-SM"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
8862474002	NO			"NETM1000-6-0-SP", "1448803-1"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9251514001	NO			"1197176-8", "V4-3/8-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5099-000	NO						
CB5105-000	NO						
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5370-000	NO						
CB5385-000	NO						
CF6155-000	NO						
CF6166-000	NO			"9-1191306-3"			
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
074977-000	NO			"9-1190560-2", "V4-1/8-0-SP"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
1630834001	NO			"1-1191177-8", "CGPT-3/1-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3421334005	NO			"3-1192579-5", "CGAT-6/2-0-SP"			
4036954002	NO			"4-1193047-7", "CGPT-1.5/0.5-0-SP"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
4613294001	NO			"3-1193460-0", "CGPT-3/1-9-SP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934055	NO			"2-1193826-6", "RNF-100-1/16-9-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053004011	NO			"1-1193835-5", "RNF-100-1/8-2-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053094080	NO			"3-1193845-6", "RNF-100-1/4-0-SP", "RNF-100-1/4-0"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053154018	NO			"6-1193857-6", "RNF-100-3/8-2-SP"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5067134001	NO			"6-1193931-2", "CGPT-76/38-6-SP"			
5069834023	NO			"9-1193949-2", "CGPT-4.8/2.4-0-SP"			
5069994004	NO			"5-1193958-8", "CGPT-19/9.5-9-SP"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5522244003	NO			"8-1194364-4", "RNF-3000-6/2-8-SP"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6339874001	NO			"6-1195014-5", "CGPT-12/4-0-SP"			
663099J001	NO			"5-1195226-9", "V2-22.0-0-FSP-SM"			
6823354001	NO			"4-1195363-0", "CGPT-6/2-0-SP"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
8862474002	NO			"NETM1000-6-0-SP", "1448803-1"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9251514001	NO			"1197176-8", "V4-3/8-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9856874001	NO			"7-1197614-1", "CGPT-12/4-9-SP"			
CB5062-000	NO			"9-1899832-1"			
CB5099-000	NO						
CB5105-000	NO						
CB5370-000	NO						
CB5385-000	NO						
CF6155-000	NO						
CF6166-000	NO			"9-1191306-3"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
NB09944001	NO						
NB10114001	NO						
NB10594001	NO						
NB11234001	NO						
NB11644001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
074977-000	NO			"9-1190560-2", "V4-1/8-0-SP"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5522244003	NO			"8-1194364-4", "RNF-3000-6/2-8-SP"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
663099J001	NO			"5-1195226-9", "V2-22.0-0-FSP-SM"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
8862474002	NO			"NETM1000-6-0-SP", "1448803-1"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9251514001	NO			"1197176-8", "V4-3/8-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5099-000	NO						
CB5105-000	NO						
CB5370-000	NO						
CB5385-000	NO						
CF6155-000	NO						
CF6166-000	NO			"9-1191306-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
074977-000	NO			"9-1190560-2", "V4-1/8-0-SP"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
1630834001	NO			"1-1191177-8", "CGPT-3/1-0-SP"			
2592854002	NO			"9-1191896-3", "NETM1000-14-0-SP"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3421334005	NO			"3-1192579-5", "CGAT-6/2-0-SP"			
4036954002	NO			"4-1193047-7", "CGPT-1.5/0.5-0-SP"			
408941-000	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
4613294001	NO			"3-1193460-0", "CGPT-3/1-9-SP"			
467437J001	NO			"6-1193503-8", "V4-8.0-0-FSP-SM"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934055	NO			"2-1193826-6", "RNF-100-1/16-9-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053004011	NO			"1-1193835-5", "RNF-100-1/8-2-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053094080	NO			"3-1193845-6", "RNF-100-1/4-0-SP", "RNF-100-1/4-0"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053154018	NO			"6-1193857-6", "RNF-100-3/8-2-SP"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5067134001	NO			"6-1193931-2", "CGPT-76/38-6-SP"			
5069834023	NO			"9-1193949-2", "CGPT-4.8/2.4-0-SP"			
5069994004	NO			"5-1193958-8", "CGPT-19/9.5-9-SP"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5522244003	NO			"8-1194364-4", "RNF-3000-6/2-8-SP"			
5634734012	NO			"ATUM-12/3-0-SP", "1642023-1"			
5677854002	NO			"2-1194506-0", "RNF-3000-6/2-9-SP"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6339874001	NO			"6-1195014-5", "CGPT-12/4-0-SP"			
663099J001	NO			"5-1195226-9", "V2-22.0-0-FSP-SM"			
6823354001	NO			"4-1195363-0", "CGPT-6/2-0-SP"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
8268294002	NO			"3-1196458-8", "NETM1000-12-0-SP"			
8862474002	NO			"NETM1000-6-0-SP", "1448803-1"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9251514001	NO			"1197176-8", "V4-3/8-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
9856874001	NO			"7-1197614-1", "CGPT-12/4-9-SP"			
CB5062-000	NO			"9-1899832-1"			
CB5099-000	NO						
CB5105-000	NO						
CB5370-000	NO						
CB5385-000	NO						
CF6155-000	NO						
CF6166-000	NO			"9-1191306-3"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB09944001	NO						
NB10114001	NO						
NB10594001	NO						
NB11234001	NO						
NB11644001	NO						