



# Product Change Notification

## TE Connectivity

Product Change Notification: P-20-018899

PCN Date: 08-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Notification of Lead Time changes due to Corona Virus impact on tubing products.

**Description of Changes**

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

**Other attachments:**

[PCN - Changes to Tubing lead times](#)

[Appliance Tubing - adjustment lead times 1](#)

[Appliance Tubing - adjustment lead times 2](#)

**Reason for Changes:**

Document clarification. The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	13-APR-2020

<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			
<a href="#">063725P017</a>	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">074713-000</a>	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
<a href="#">1298474001</a>	NO			"9-1190942-6", "LSTT-19-6-SP"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
<a href="#">182083-000</a>	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
<a href="#">185555-000</a>	NO			"7-1191347-0", "RBK-105-KIT-0103-A0"			
<a href="#">2187834001</a>	NO			"2-1191614-1", "CGPT-39/13-X-SP"			
<a href="#">2748174003</a>	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
<a href="#">2881454003</a>	NO			"5-1192185-2", "LSTT-25.4-4-SP"			
<a href="#">3647544004</a>	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
<a href="#">3830054001</a>	NO			"1192870-3", "LSTT-19-9-SP"			
<a href="#">4177514031</a>	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">449582-000</a>	NO			"8-1200740-7", "VERSAFIT-MINI-SPL-3/4-BK"			
<a href="#">5020054016</a>	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
<a href="#">5020114003</a>	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5052894108</a>	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
<a href="#">5053244040</a>	NO			"3-1193869-5", "RNF-100-3/4-0-SP"			
<a href="#">5053294053</a>	NO			"4-1193876-8", "RNF-100-1-0-SP"			
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">5053384013</a>	NO			"3-1193885-2", "RNF-100-1-1/2-9-SP"			
<a href="#">5053404004</a>	NO			"4-1193886-7", "RNF-100-2-2-SP"			
<a href="#">5053424005</a>	NO			"1193887-3", "RNF-100-2-6-SP"			
<a href="#">5067454043</a>	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
<a href="#">5068184005</a>	NO			"3-1193938-7", "CGPT-4.8/2.4-4-SP"			
<a href="#">5068234005</a>	NO			"3-1193939-9", "CGPT-25.4/12.7-4-SP"			
<a href="#">5068304007</a>	NO			"3-1193940-9", "CGPT-4.8/2.4-6-SP"			
<a href="#">5069884015</a>	NO			"8-1193954-3", "CGPT-25.4/12.7-0-SP"			
<a href="#">5070104028</a>	NO			"8-1193967-7", "RNF-100-1-X-SP"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0-STK"			
<a href="#">5509114058</a>	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
<a href="#">5628374001</a>	NO			"9-1194446-7", "LSTT-32-0-SP"			
<a href="#">5677744002</a>	NO			"1194503-1", "RNF-3000-24/8-4-SP"			
<a href="#">5677954003</a>	NO			"8-1194510-8", "RNF-3000-24/8-X-SP"			
<a href="#">5765954007</a>	NO			"3-1194574-8", "RT-375-3/8-X-SP"			
<a href="#">6106994002</a>	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
<a href="#">6645974001</a>	NO			"9-1195236-9", "ZH-100-3/4-0-SP"			
<a href="#">7024702003</a>	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
<a href="#">710215-000</a>	NO			"3-1195564-6", "RBK-105-KIT-0504-A0"			
<a href="#">7465234002</a>	NO			"8-1195823-0", "HTAT-12/3-0-SP"			
<a href="#">7501716003</a>	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
<a href="#">8923464003</a>	NO			"1448964-1", "VERSAFIT-1/8-4-SP"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">9264634014</a>	NO			"5-1201445-0", "ATUM-12/4-X-SP"			
<a href="#">968711-000</a>	NO			"6-1197489-0", "RBK-85-KIT-0203-A0"			
<a href="#">A66551-000</a>	NO			"1200741-5", "RNF-100-MINI-SPL-1/16-BK"			
<a href="#">C16404-000</a>	NO			"2-1200741-4", "VERSAFIT-MINI-SPL-3/64-BK"			
<a href="#">C17600-000</a>	NO			"2-1200741-5", "VERSAFIT-MINI-SPL-1/8-BK", "16-0256"			
<a href="#">C53800-000</a>	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			
<a href="#">C72402-000</a>	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
<a href="#">C87605-000</a>	NO			"8-1200721-3", "VERSAFIT-1/4-KT2-REFILL"			
<a href="#">CB5052-000</a>	NO			"6-1899211-8", "BSTS-17X4"			
<a href="#">CB5122-000</a>	NO			"HRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CB5129-000</a>	NO			"HRHF-250FR-10/97"			
<a href="#">CH03642001</a>	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
<a href="#">CV25362001</a>	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
<a href="#">CV3301-000</a>	NO			"RW-175-3/32-X-STK", "16-0114"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			
<a href="#">CV4356-000</a>	NO			"HT-200-3/32-X-SP"			
<a href="#">CV4357-000</a>	NO			"HT-200-1/8-X-SP"			
<a href="#">CV4363-000</a>	NO			"HT-200-1-X-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">D68311-000</a>	NO			"9-1202026-1", "RNF-100-1/4-BK-SP-CS7797"			
<a href="#">EG40970001</a>	NO						
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">NB07066001</a>	NO			"BATTU-12.7/6.1-A1-0-32MM"			
<a href="#">NB07106001</a>	NO			"8-1899840-2", "BATTU-20.1/8.9-A1-0-39MM"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
<a href="#">NB07246001</a>	NO			"BATTU-20.1/8.9-A1-2-77MM"			
<a href="#">NB07266001</a>	NO			"BATTU-25.4/12.7A1-2-102MM"			
<a href="#">NB09542001</a>	NO			"ATUM--16/4-0-STK"			
<a href="#">NB09654001</a>	NO						
<a href="#">NB14134001</a>	NO						
<a href="#">NB14164001</a>	NO						
<a href="#">NB14554001</a>	NO						
<a href="#">NB14654001</a>	NO						
<a href="#">NB14674001</a>	NO						
<a href="#">NB14902001</a>	NO						
<a href="#">NB14912001</a>	NO						
<a href="#">NB15014001</a>	NO						
<a href="#">NB15184001</a>	NO						
<a href="#">NB15694001</a>	NO						
<a href="#">NB15734001</a>	NO						
<a href="#">NB15784001</a>	NO						
<a href="#">NB16622001</a>	NO						
<a href="#">NB16934001</a>	NO						
<a href="#">NB17012001</a>	NO						
<a href="#">NB17724001</a>	NO						
<a href="#">NB17754001</a>	NO						
<a href="#">NB17872001</a>	NO						
<a href="#">NB17932001</a>	NO						
<a href="#">NB18884001</a>	NO						
<a href="#">NB20124001</a>	NO						
<a href="#">NB20214001</a>	NO						
<a href="#">NB20344001</a>	NO						
<a href="#">NB20364001</a>	NO						
<a href="#">NB20504001</a>	NO						
<a href="#">NB25802001</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
<a href="#">182083-000</a>	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
<a href="#">2748174003</a>	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
<a href="#">3647544004</a>	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">449582-000</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"8-1200740-7", "VERSAFIT-MINI-SPL-3/4-BK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5052894108</a>	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
<a href="#">5765954007</a>	NO			"3-1194574-8", "RT-375-3/8-X-SP"			
<a href="#">7024702003</a>	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
<a href="#">A66551-000</a>	NO			"1200741-5", "RNF-100-MINI-SPL-1/16-BK"			
<a href="#">C16404-000</a>	NO			"2-1200741-4", "VERSAFIT-MINI-SPL-3/64-BK"			
<a href="#">C17600-000</a>	NO			"2-1200741-5", "VERSAFIT-MINI-SPL-1/8-BK", "16-0256"			
<a href="#">C53800-000</a>	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			
<a href="#">C72402-000</a>	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
<a href="#">C87605-000</a>	NO			"8-1200721-3", "VERSAFIT-1/4-KT2-REFILL"			
<a href="#">CB5052-000</a>	NO			"6-1899211-8", "BSTS-17X4"			
<a href="#">CB5122-000</a>	NO			"HRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CV3301-000</a>	NO			"RW-175-3/32-X-STK", "16-0114"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			
<a href="#">CV4363-000</a>	NO			"HT-200-1-X-SP"			
<a href="#">D68311-000</a>	NO			"9-1202026-1", "RNF-100-1/4-BK-SP-CS7797"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">NB07066001</a>	NO			"BATTU-12.7/6.1-A1-0-32MM"			
<a href="#">NB07106001</a>	NO			"8-1899840-2", "BATTU-20.1/8.9-A1-0-39MM"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
<a href="#">NB07246001</a>	NO			"BATTU-20.1/8.9-A1-2-77MM"			
<a href="#">NB07266001</a>	NO			"BATTU-25.4/12.7A1-2-102MM"			
<a href="#">NB09542001</a>	NO			"ATUM--16/4-0-STK"			
<a href="#">NB14134001</a>	NO						
<a href="#">NB14902001</a>	NO						
<a href="#">NB14912001</a>	NO						
<a href="#">NB15184001</a>	NO						
<a href="#">NB15734001</a>	NO						
<a href="#">NB15784001</a>	NO						
<a href="#">NB16622001</a>	NO						
<a href="#">NB16934001</a>	NO						
<a href="#">NB17754001</a>	NO						
<a href="#">NB17932001</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">074713-000</a>	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
<a href="#">4177514031</a>	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
<a href="#">5020054016</a>	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
<a href="#">5020114003</a>	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5067454043</a>	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
<a href="#">5509114058</a>	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
<a href="#">5677954003</a>	NO			"8-1194510-8", "RNF-3000-24/8-X-SP"			
<a href="#">7465234002</a>	NO			"8-1195823-0", "HTAT-12/3-0-SP"			
<a href="#">8923464003</a>	NO			"1448964-1", "VERSAFIT-1/8-4-SP"			
<a href="#">CB5122-000</a>	NO			"HRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CB5129-000</a>	NO			"HRHF-250FR-10/97"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">074713-000</a>	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			
<a href="#">182083-000</a>	NO			"2-1191323-8", "VERSAFIT-1-0-FSP"			
<a href="#">2748174003</a>	NO			"5-1192035-7", "VERSAFIT-3/32-6-SP"			
<a href="#">3647544004</a>	NO			"4-1192735-1", "VERSAFIT-1-1/4-0-SP"			
<a href="#">4177514031</a>	NO			"7-1193147-1", "ATUM-24/6-0-SP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">449582-000</a>	NO			"8-1200740-7", "VERSAFIT-MINI-SPL-3/4-BK"			
<a href="#">5020054016</a>	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
<a href="#">5020114003</a>	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5067454043</a>	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
<a href="#">5509114058</a>	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
<a href="#">5677954003</a>	NO			"8-1194510-8", "RNF-3000-24/8-X-SP"			
<a href="#">5765954007</a>	NO			"3-1194574-8", "RT-375-3/8-X-SP"			
<a href="#">6106994002</a>	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
<a href="#">7024702003</a>	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
<a href="#">7465234002</a>	NO			"8-1195823-0", "HTAT-12/3-0-SP"			
<a href="#">8923464003</a>	NO			"1448964-1", "VERSAFIT-1/8-4-SP"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">A66551-000</a>	NO			"1200741-5", "RNF-100-MINI-SPL-1/16-BK"			
<a href="#">C16404-000</a>	NO			"2-1200741-4", "VERSAFIT-MINI-SPL-3/64-BK"			
<a href="#">C17600-000</a>	NO			"2-1200741-5", "VERSAFIT-MINI-SPL-1/8-BK", "16-0256"			
<a href="#">C53800-000</a>	NO			"7-1200721-2", "VERSAFIT-3/16-KT2-REFILL"			
<a href="#">C72402-000</a>	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			
<a href="#">CB5052-000</a>	NO			"6-1899211-8", "BSTS-17X4"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5122-000</a>	NO			"HRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CB5129-000</a>	NO			"HRHF-250FR-10/97"			
<a href="#">CV3301-000</a>	NO			"RW-175-3/32-X-STK", "16-0114"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			
<a href="#">CV4363-000</a>	NO			"HT-200-1-X-SP"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">NB07066001</a>	NO			"BATTU-12.7/6.1-A1-0-32MM"			
<a href="#">NB07106001</a>	NO			"8-1899840-2", "BATTU- 20.1/8.9-A1-0-39MM"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
<a href="#">NB07246001</a>	NO			"BATTU-20.1/8.9-A1-2-77MM"			
<a href="#">NB07266001</a>	NO			"BATTU-25.4/12.7A1-2-102MM"			
<a href="#">NB09542001</a>	NO			"ATUM--16/4-0-STK"			
<a href="#">NB14912001</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">074713-000</a>	NO			"1190559-5", "VERSAFIT-3/4-4- FSP"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16- 0-SP"			
<a href="#">185555-000</a>	NO			"7-1191347-0", "RBK-105-KIT- 0103-A0"			
<a href="#">5020054016</a>	NO			"5-1193753-7", "RP-4800- NO.4-0-SP"			
<a href="#">5020114003</a>	NO			"8-1193753-7", "RP-4800- NO.9-0-SP"			
<a href="#">5052894108</a>	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
<a href="#">5053244040</a>	NO			"3-1193869-5", "RNF-100-3/4-0- SP"			
<a href="#">5053294053</a>	NO			"4-1193876-8", "RNF-100-1-0- SP"			
<a href="#">5067454043</a>	NO			"1-1193933-1", "ATUM-19/6-0- SP", "ATUM-19/6-0"			
<a href="#">5068184005</a>	NO			"3-1193938-7", "CGPT-4.8/2.4-4- SP"			
<a href="#">5069884015</a>	NO			"8-1193954-3", "CGPT- 25.4/12.7-0-SP"			
<a href="#">5070104028</a>	NO			"8-1193967-7", "RNF-100-1-X- SP"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2- STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0- STK"			
<a href="#">5509114058</a>	NO			"7-1194351-6", "ATUM-24/8-0- SP"			
<a href="#">5628374001</a>	NO			"9-1194446-7", "LSTT-32-0-SP"			
<a href="#">5677744002</a>	NO			"1194503-1", "RNF-3000-24/8-4- SP"			
<a href="#">5677954003</a>	NO			"8-1194510-8", "RNF-3000- 24/8-X-SP"			
<a href="#">6106994002</a>	NO			"4-1194829-3", "ATUM-24/8-2- SP"			
<a href="#">710215-000</a>	NO			"3-1195564-6", "RBK-105-KIT- 0504-A0"			
<a href="#">7465234002</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"8-1195823-0", "HTAT-12/3-0-SP"			
<a href="#">7501716003</a>	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
<a href="#">8923464003</a>	NO			"1448964-1", "VERSAFIT-1/8-4-SP"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">9264634014</a>	NO			"5-1201445-0", "ATUM-12/4-X-SP"			
<a href="#">968711-000</a>	NO			"6-1197489-0", "RBK-85-KIT-0203-A0"			
<a href="#">CB5122-000</a>	NO			"HRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CB5129-000</a>	NO			"HRHF-250FR-10/97"			
<a href="#">CH03642001</a>	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
<a href="#">CV25362001</a>	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
<a href="#">CV3301-000</a>	NO			"RW-175-3/32-X-STK", "16-0114"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			
<a href="#">CV4356-000</a>	NO			"HT-200-3/32-X-SP"			
<a href="#">CV4357-000</a>	NO			"HT-200-1/8-X-SP"			
<a href="#">CV4363-000</a>	NO			"HT-200-1-X-SP"			
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">NB07066001</a>	NO			"BATTU-12.7/6.1-A1-0-32MM"			
<a href="#">NB07106001</a>	NO			"8-1899840-2", "BATTU-20.1/8.9-A1-0-39MM"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
<a href="#">NB09654001</a>	NO						
<a href="#">NB15784001</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P017</a>	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">C72402-000</a>	NO			"7-1200726-2", "VERSAFIT-KIT-6-0"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">030791-000</a>	NO			"7-1190238-4"			
<a href="#">074713-000</a>	NO			"1190559-5", "VERSAFIT-3/4-4-FSP"			
<a href="#">1298474001</a>	NO			"9-1190942-6", "LSTT-19-6-SP"			
<a href="#">1637114002</a>	NO			"4-1191181-6", "RNF-150-1/16-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">185555-000</a>	NO			"7-1191347-0", "RBK-105-KIT-0103-A0"			
<a href="#">2187834001</a>	NO			"2-1191614-1", "CGPT-39/13-X-SP"			
<a href="#">2881454003</a>	NO			"5-1192185-2", "LSTT-25.4-4-SP"			
<a href="#">3830054001</a>	NO			"1192870-3", "LSTT-19-9-SP"			
<a href="#">5020054016</a>	NO			"5-1193753-7", "RP-4800-NO.4-0-SP"			
<a href="#">5020114003</a>	NO			"8-1193753-7", "RP-4800-NO.9-0-SP"			
<a href="#">5052894108</a>	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
<a href="#">5053244040</a>	NO			"3-1193869-5", "RNF-100-3/4-0-SP"			
<a href="#">5053294053</a>	NO			"4-1193876-8", "RNF-100-1-0-SP"			
<a href="#">5053384013</a>	NO			"3-1193885-2", "RNF-100-1-1/2-9-SP"			
<a href="#">5053404004</a>	NO			"4-1193886-7", "RNF-100-2-2-SP"			
<a href="#">5053424005</a>	NO			"1193887-3", "RNF-100-2-6-SP"			
<a href="#">5067454043</a>	NO			"1-1193933-1", "ATUM-19/6-0-SP", "ATUM-19/6-0"			
<a href="#">5068184005</a>	NO			"3-1193938-7", "CGPT-4.8/2.4-4-SP"			
<a href="#">5068234005</a>	NO			"3-1193939-9", "CGPT-25.4/12.7-4-SP"			
<a href="#">5068304007</a>	NO			"3-1193940-9", "CGPT-4.8/2.4-6-SP"			
<a href="#">5069884015</a>	NO			"8-1193954-3", "CGPT-25.4/12.7-0-SP"			
<a href="#">5070104028</a>	NO			"8-1193967-7", "RNF-100-1-X-SP"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0-STK"			
<a href="#">5509114058</a>	NO			"7-1194351-6", "ATUM-24/8-0-SP"			
<a href="#">5628374001</a>	NO			"9-1194446-7", "LSTT-32-0-SP"			
<a href="#">5677744002</a>	NO			"1194503-1", "RNF-3000-24/8-4-SP"			
<a href="#">5677954003</a>	NO			"8-1194510-8", "RNF-3000-24/8-X-SP"			
<a href="#">6106994002</a>	NO			"4-1194829-3", "ATUM-24/8-2-SP"			
<a href="#">6645974001</a>	NO			"9-1195236-9", "ZH-100-3/4-0-SP"			
<a href="#">710215-000</a>	NO			"3-1195564-6", "RBK-105-KIT-0504-A0"			
<a href="#">7465234002</a>	NO			"8-1195823-0", "HTAT-12/3-0-SP"			
<a href="#">7501716003</a>	NO			"3-1195850-2", "RBK-ILS-125-NR4-0-75MM"			
<a href="#">8923464003</a>	NO			"1448964-1", "VERSAFIT-1/8-4-SP"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">9264634014</a>	NO			"5-1201445-0", "ATUM-12/4-X-SP"			
<a href="#">968711-000</a>	NO			"6-1197489-0", "RBK-85-KIT-0203-A0"			
<a href="#">CB5122-000</a>	NO			"HRRHF-200FR-10/97", "5-1192468-6"			
<a href="#">CB5129-000</a>	NO			"HRRHF-250FR-10/97"			
<a href="#">CH03642001</a>	NO			"QSZH-125-NR4-STK", "2-1899487-5"			



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CV25362001</a>	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
<a href="#">CV3301-000</a>	NO			"RW-175-3/32-X-STK", "16-0114"			
<a href="#">CV4355-000</a>	NO			"HT-200-1/16-X-SP"			
<a href="#">CV4356-000</a>	NO			"HT-200-3/32-X-SP"			
<a href="#">CV4357-000</a>	NO			"HT-200-1/8-X-SP"			
<a href="#">CV4363-000</a>	NO			"HT-200-1-X-SP"			
<a href="#">EG40970001</a>	NO						
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">NB07066001</a>	NO			"BATTU-12.7/6.1-A1-0-32MM"			
<a href="#">NB07106001</a>	NO			"8-1899840-2", "BATTU- 20.1/8.9-A1-0-39MM"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			
<a href="#">NB09654001</a>	NO						
<a href="#">NB14164001</a>	NO						
<a href="#">NB14554001</a>	NO						
<a href="#">NB14654001</a>	NO						
<a href="#">NB14674001</a>	NO						
<a href="#">NB15014001</a>	NO						
<a href="#">NB15694001</a>	NO						
<a href="#">NB15784001</a>	NO						
<a href="#">NB17012001</a>	NO						
<a href="#">NB17724001</a>	NO						
<a href="#">NB17872001</a>	NO						
<a href="#">NB18884001</a>	NO						
<a href="#">NB20124001</a>	NO						
<a href="#">NB20214001</a>	NO						
<a href="#">NB20344001</a>	NO						
<a href="#">NB20364001</a>	NO						
<a href="#">NB20504001</a>	NO						
<a href="#">NB25802001</a>	NO						