

<b>DELKIN DEVICES</b>	<b>EOL NOTIFICATION</b>		
	<b>DOCUMENT TITLE: EOL Notification – Utility/Utility+ 2D MLC SSDs</b>		
<b>DEPT: Marketing</b>	<b>DOCUMENT NO.</b>	<b>412-0069-00</b>	
<b>PRINT DATE: 4/23/2021</b>	<b>REV</b>	<b>A</b>	<b>Page 1 of 3</b>

**REVISION HISTORY**

<b>REV</b>	<b>DESCRIPTION OF CHANGE</b>	<b>DATE</b>	<b>CHANGE REQUEST #</b>
A	Initial Release	4/30/2021	NA

**Title of EOL: Utility/Utility+ 2D MLC SSD's**

**Date: 04/30/2021**  
**EOL No: 412-0069-00**

**EOL Effective Date: 04/30/2021**

**Last Time Buy Date: 7/30/2021**  
**Last Time Ship Date: 10/29/2021**

**Description:**

Delkin Devices is announcing end of life on current 2D MLC Utility / Utility+ Series SATA SSD products, thereby consolidating our product offering to mainstream 3D NAND configurations.

**Products Affected:**

See part number list on pages 2 and 3.

**Impact of Change:**

The EOL part numbers listed on the following pages will no longer be available for purchase after the Last Time Ship date. Replacement part numbers utilizing 3D NAND are available, as shown on in the table on pages 2 and 3.

**Reference Documents/Attachments:**

Delkin Devices Engineering Specifications are available for download at [www.delkin.com](http://www.delkin.com) or from your Delkin sales representative.

**Qualification Samples:**

Contact your Delkin sales representative to arrange new qualification samples.

Any additional questions that are not covered in this notification can be addressed by your Delkin Sales Representative.

Sincerely,



Tina Guidotti  
Director of Product Management and Technical Support  
Delkin Devices, Inc.

**Part Numbers Affected by this End of Life Notification**

<b>EOL Part Number</b>	<b>Replacement Part Number</b>	<b>EOL Part Number</b>	<b>Replacement Part Number</b>
BA08AJZB6-XN000-2	Contact Delkin	DE2TAPXCM-35000-2	DE2TFQXGJ-35000-2
BA08AJZB6-XN000-P	Contact Delkin	DE2TAPXD8-35000-2	Contact Delkin
BA16AKED6-XN000-2	Contact Delkin	DE2TAPXDX-35000-2	DE2TFQXGJ-35000-2
BA16AKED6-XN000-P	Contact Delkin	DE2TAPXDX-35050-2	Contact Delkin
BA16APSC2-XN000-2	Contact Delkin	DE32APRD6-35000-2	DE32FQQFC-35000-2
BA16APSC2-XN000-P	Contact Delkin	DE32APT5U-35000-P	DE32FQQFC-35000-2
BA16APSD6-XN000-P	Contact Delkin	DE5HAPW6P-35000-2	DE5HFQXFC-35000-2
BA32AQED6-XN000-2	Contact Delkin	DE5HAPW6P-35050-2	Contact Delkin
BA32AQED6-XN000-P	Contact Delkin	DE5HAPWDL-35000-2	DE5HFQXFC-35000-2
BA64AQED6-XN000-2	Contact Delkin	DE5HAPWDL-35162-2	Contact Delkin
BA64AQED6-XN000-P	Contact Delkin	DE5HAPWGW-35000-2	DE5HFQXFC-35000-2
BE1HAPWGB-3N000-2	Contact Delkin	DE5HAPXAP-35137-2	Contact Delkin
BE1HAPWGB-3N000-P	Contact Delkin	DE5HAPXAP-35137-P	Contact Delkin
BE32APCD6-3N000-2	Contact Delkin	DE5HAPXBN-35137-2	Contact Delkin
BE32APCD6-3N000-P	Contact Delkin	DE5HAPXBN-35137-P	Contact Delkin
BE64APCEP-3N000-2	Contact Delkin	DE64APR5V-35000-P	DE64FQQFC-35000-2
BE64APCEP-3N000-P	Contact Delkin	DE64APR6P-35000-2	DE64FQQFC-35000-2
DE1HANAU4-35000-2	DE1HFQQFC-35000-2	DE64APR6P-35050-2	Contact Delkin
DE1HAPB6P-35000-2	DE1HFQQFC-35000-2	DE64APRDL-35000-2	DE64FQQFC-35000-2
DE1HAPR6P-35000-2	DE1HFQQFC-35000-2	DE64APRDL-35050-2	Contact Delkin
DE1HAPR6P-35050-2	Contact Delkin	DE64APRGW-35000-2	DE64FQQFC-35000-2
DE1HAPRDL-35000-2	DE1HFQQFC-35000-2	DS1HAMDU4-35000-2	Contact Delkin
DE1HAPRGW-35000-2	DE1HFQQFC-35000-2	DS1HAMDU4-37000-2	Contact Delkin
DE1TAMSU4-35000-2	DE1TFRAFC-35000-2	DS1HAPB6P-35000-2	Contact Delkin
DE1TAPX6P-35000-2	DE1TFRAFC-35000-2	DS1TAMSU4-35000-2	Contact Delkin
DE1TAPX6P-35050-2	Contact Delkin	DS2HAMDU4-35000-2	Contact Delkin
DE1TAPXBH-35000-2	DE1TFRAFC-35000-2	DS2HAMXU4-37000-2	Contact Delkin
DE1TAPXD7-35000-2	Contact Delkin	DS2HAQE6P-35192-P	Contact Delkin
DE1TAPXDL-35000-2	DE1TFRAFC-35000-2	DS32AMQU4-37000-2	Contact Delkin
DE1TAPXDL-35050-2	Contact Delkin	DS5HAMXU4-35000-2	Contact Delkin
DE1TAPXGW-35000-2	DE1TFRAFC-35000-2	DS64AMDCX-25000-2	Contact Delkin
DE2HAMPU4-37000-2	DE2HFQXFC-35000-2	DS64AMDCX-25000-P	Contact Delkin
DE2HAMPU4-37171-2	Contact Delkin	DS64AMQU4-35000-2	Contact Delkin
DE2HAPC6P-35000-2	DE2HFQXFC-35000-2	DS64AMQU4-37000-2	Contact Delkin
DE2HAPC6P-35050-2	Contact Delkin	MB1HAPCBN-80000-2	MB1HFQQFZ-80000-2
DE2HAPCD7-35000-2	Contact Delkin	MB1HAPW7C-60000-2	Contact Delkin
DE2HAPCDL-35000-2	DE2HFQXFC-35000-2	MB1HAPWBN-42000-2	MB1HFRCFZ-42000-2
DE2HAPWBF-35137-P	Contact Delkin	MB2HAPW5U-80000-2	MB2HFQXFZ-80000-2
DE2HAPWBN-35137-2	Contact Delkin	MB2HAPWBN-80000-2	MB2HFQXFZ-80000-2
DE2HAPWBN-35137-P	Contact Delkin	MB2HAPX7C-60000-2	Contact Delkin
DE2TAPX7R-35000-2	DE2TFQXGJ-35000-2	MB2HAPXBN-42000-2	MB2HFQXFZ-42000-2
DE2TAPX7R-35050-2	Contact Delkin	MB5HAPXBF-80000-2	MB5HFQXFZ-80000-2

**Part Numbers Affected by this End of Life Notification**

EOL Part Number	Replacement Part Number	EOL Part Number	Replacement Part Number
MB5HAPXBN-80000-2	MB5HFQXFZ-80000-2	MD5HAPX5X-3N188-2	Contact Delkin
MB5HAPXBN-80106-2	Contact Delkin	MD5HAPX5X-3NA88-2	Contact Delkin
MB64APBBN-80000-2	MB1HFQQFZ-80000-2	MD5HAPXA3-3NA88-2	Contact Delkin
MB64APRBN-80000-2	MB1HFQQFZ-80000-2	MD5HAPXA3-3NB88-2	Contact Delkin
MC16AQFJC-42000-2	Contact Delkin	MD64AMDUV-3N000-2	MD64FNUFC-3N000-2
MC2HAPX66-42000-2	Contact Delkin	MD64AMDUV-3N000-P	MD64FNUFC-3N000-2
MD16AMQUV-3N000-2	MD32FNUFC-3N000-2	MD64APB4R-3N000-2	MD64FNUFC-3N000-2
MD16AMQUV-3N000-P	MD32FNUFC-3N000-2	ME1HAPC5U-3N000-2	ME1HFQQFC-3N000-2
MD1HAMXUV-3N000-2	MD1HFNWFC-3N000-2	ME2HANEYQ-3N000-2	ME2HFQXFC-3N000-2
MD1HAMXUV-3N000-P	MD1HFNWFC-3N000-2	ME2HANEYQ-3N000-P	ME2HFQXFC-3N000-2
MD1HAPC5X-3N000-2	MD1HFNWFC-3N000-2	ME2HAPW5U-3N000-2	ME2HFQXFC-3N000-2
MD1HAPC5X-3N000-P	MD1HFNWFC-3N000-2	ME2HAPW5U-3N048-2	Contact Delkin
MD1HAPCAP-3N188-2	Contact Delkin	ME32ANBUZ-3N000-2	ME32FQQFC-3N000-2
MD1HAPCGT-3N000-2	MD1HFNWFC-3N000-2	ME32ANBUZ-3N000-P	ME32FQQFC-3N000-2
MD1TAQL7W-3N000-2	MD1TFNXFC-3N000-2	ME32APT5U-3N000-2	ME32FQQFC-3N000-2
MD1TAQL7W-3N188-2	Contact Delkin	ME5HAPX7V-3N000-2	ME5HFQXFC-3N000-2
MD2HANEUV-3N000-2	MD2HFLGFC-3N000-2	ME5HAPX7V-3N048-2	Contact Delkin
MD2HANEUV-3N000-P	MD2HFLGFC-3N000-2	ME5HAPXBF-3N000-2	ME5HFQXFC-3N000-2
MD2HAPW5X-3N000-2	MD2HFLGFC-3N000-2	ME5HAPXBN-3N000-2	ME5HFQXFC-3N000-2
MD2HAPW5X-3N000-P	MD2HFLGFC-3N000-2	ME5HAPXBN-3N048-2	Contact Delkin
MD2HAPW5X-3N188-2	Contact Delkin	ME64ANAUV-3N000-2	ME64FQQFC-3N000-2
MD2HAPWAP-3N188-2	Contact Delkin	ME64ANAUV-3N000-P	ME64FQQFC-3N000-2
MD32AFQQ7-XX000-P	MD32FNUFC-3N000-2	ME64APR5U-3N000-2	ME64FQQFC-3N000-2
MD32AMQUV-3N000-2	MD32FNUFC-3N000-2	ME64APR5U-3N000-P	ME64FQQFC-3N000-2
MD32AMQUV-3N000-P	MD32FNUFC-3N000-2	MK32APS5U-3N000-2	Contact Delkin
MD32APS4R-3N000-2	MD32FNUFC-3N000-2	MN64APCAH-3N000-2	Contact Delkin
MD5HAPX5X-3N000-2	MD5HFLGFC-3N000-2	MQ32APB4R-3N000-2	Contact Delkin
MD5HAPX5X-3N000-P	MD5HFLGFC-3N000-2	MQ32APB4R-3N000-P	Contact Delkin