



## Product Obsolescence Notification (PON)

Issue Date: June 23, 2014

PON #: OBS05212014OC4

Dear Customer,

Avago Technologies announces the obsolescence of a list of legacy EML packages due to low volume. This obsolescence will apply to the part numbers in the table below.

The key milestones are:

1. Final customer order date on or before September 24, 2014
2. Final ship date to customer on or before December 24, 2014

Orders are non-cancelable, non-returnable.

Please note that Avago Technologies reserves the right to limit last time buy quantities based on capacity and material availability.

There are no replacement part numbers for these EML legacy packages.

If you have any questions about this obsolescence, please do not hesitate to contact your local Avago Technologies sales representative or authorized distributors.

**Avago Technologies**  
**Fiber Optics Product Division**  
350 West Trimble Road  
San Jose, CA 95131  
U.S.A.

Current part number	Description	Recommended replacement number
E2502S22	2.5G 1.5um EML in butterfly package	No replacement
E2502S23	2.5G 1.5um EML in butterfly package	No replacement
E2502S24	2.5G 1.5um EML in butterfly package	No replacement
E2502S25	2.5G 1.5um EML in butterfly package	No replacement
E2502S26	2.5G 1.5um EML in butterfly package	No replacement
E2502S27	2.5G 1.5um EML in butterfly package	No replacement
E2502S28	2.5G 1.5um EML in butterfly package	No replacement
E2502S29	2.5G 1.5um EML in butterfly package	No replacement
E2502S30	2.5G 1.5um EML in butterfly package	No replacement
E2502S32	2.5G 1.5um EML in butterfly package	No replacement
E2502S35	2.5G 1.5um EML in butterfly package	No replacement
E2502S36	2.5G 1.5um EML in butterfly package	No replacement

---

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.



<b>Current part number</b>	<b>Description</b>	<b>Recommended replacement number</b>
E2502S37	2.5G 1.5um EML in butterfly package	No replacement
E2502S38	2.5G 1.5um EML in butterfly package	No replacement
E2502S39	2.5G 1.5um EML in butterfly package	No replacement
E2502S40	2.5G 1.5um EML in butterfly package	No replacement
E2502S41	2.5G 1.5um EML in butterfly package	No replacement
E2502S43	2.5G 1.5um EML in butterfly package	No replacement
E2502S44	2.5G 1.5um EML in butterfly package	No replacement
E2502S45	2.5G 1.5um EML in butterfly package	No replacement
E2502S46	2.5G 1.5um EML in butterfly package	No replacement
E2502S47	2.5G 1.5um EML in butterfly package	No replacement
E2502S48	2.5G 1.5um EML in butterfly package	No replacement
E2502S49	2.5G 1.5um EML in butterfly package	No replacement
E2502S51	2.5G 1.5um EML in butterfly package	No replacement
E2502S54	2.5G 1.5um EML in butterfly package	No replacement
E2502S55	2.5G 1.5um EML in butterfly package	No replacement
E2502S56	2.5G 1.5um EML in butterfly package	No replacement
E2502S59	2.5G 1.5um EML in butterfly package	No replacement
E2505H	2.5G 1.5um EML in butterfly package	No replacement
E2505H19	2.5G 1.5um EML in butterfly package	No replacement
E2505H20	2.5G 1.5um EML in butterfly package	No replacement
E2505H21	2.5G 1.5um EML in butterfly package	No replacement
E2505H22	2.5G 1.5um EML in butterfly package	No replacement
E2505H23	2.5G 1.5um EML in butterfly package	No replacement
E2505H24	2.5G 1.5um EML in butterfly package	No replacement
E2505H25	2.5G 1.5um EML in butterfly package	No replacement
E2505H26	2.5G 1.5um EML in butterfly package	No replacement
E2505H27	2.5G 1.5um EML in butterfly package	No replacement
E2505H28	2.5G 1.5um EML in butterfly package	No replacement
E2505H29	2.5G 1.5um EML in butterfly package	No replacement
E2505H30	2.5G 1.5um EML in butterfly package	No replacement
E2505H31	2.5G 1.5um EML in butterfly package	No replacement
E2505H32	2.5G 1.5um EML in butterfly package	No replacement
E2505H33	2.5G 1.5um EML in butterfly package	No replacement
E2505H34	2.5G 1.5um EML in butterfly package	No replacement
E2505H35	2.5G 1.5um EML in butterfly package	No replacement
E2505H36	2.5G 1.5um EML in butterfly package	No replacement
E2505H37	2.5G 1.5um EML in butterfly package	No replacement
E2505H38	2.5G 1.5um EML in butterfly package	No replacement
E2505H39	2.5G 1.5um EML in butterfly package	No replacement
E2505H40	2.5G 1.5um EML in butterfly package	No replacement

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.

<b>Current part number</b>	<b>Description</b>	<b>Recommended replacement number</b>
E2505H41	2.5G 1.5um EML in butterfly package	No replacement
E2505H42	2.5G 1.5um EML in butterfly package	No replacement
E2505H43	2.5G 1.5um EML in butterfly package	No replacement
E2505H44	2.5G 1.5um EML in butterfly package	No replacement
E2505H45	2.5G 1.5um EML in butterfly package	No replacement
E2505H46	2.5G 1.5um EML in butterfly package	No replacement
E2505H47	2.5G 1.5um EML in butterfly package	No replacement
E2505H48	2.5G 1.5um EML in butterfly package	No replacement
E2505H49	2.5G 1.5um EML in butterfly package	No replacement
E2505H50	2.5G 1.5um EML in butterfly package	No replacement
E2505H51	2.5G 1.5um EML in butterfly package	No replacement
E2505H52	2.5G 1.5um EML in butterfly package	No replacement
E2505H53	2.5G 1.5um EML in butterfly package	No replacement
E2505H54	2.5G 1.5um EML in butterfly package	No replacement
E2505H55	2.5G 1.5um EML in butterfly package	No replacement
E2505H56	2.5G 1.5um EML in butterfly package	No replacement
E2505H57	2.5G 1.5um EML in butterfly package	No replacement
E2505H58	2.5G 1.5um EML in butterfly package	No replacement
E2505H59	2.5G 1.5um EML in butterfly package	No replacement
E2505H60	2.5G 1.5um EML in butterfly package	No replacement
E2505H61	2.5G 1.5um EML in butterfly package	No replacement
E2560D	10G 1.5um EML in half-butterfly package	No replacement
E2560D21	10G 1.5um EML in half-butterfly package	No replacement
E2560D22	10G 1.5um EML in half-butterfly package	No replacement
E2560D23	10G 1.5um EML in half-butterfly package	No replacement
E2560D24	10G 1.5um EML in half-butterfly package	No replacement
E2560D25	10G 1.5um EML in half-butterfly package	No replacement
E2560D26	10G 1.5um EML in half-butterfly package	No replacement
E2560D27	10G 1.5um EML in half-butterfly package	No replacement
E2560D28	10G 1.5um EML in half-butterfly package	No replacement
E2560D29	10G 1.5um EML in half-butterfly package	No replacement
E2560D30	10G 1.5um EML in half-butterfly package	No replacement
E2560D31	10G 1.5um EML in half-butterfly package	No replacement
E2560D32	10G 1.5um EML in half-butterfly package	No replacement
E2560D33	10G 1.5um EML in half-butterfly package	No replacement
E2560D34	10G 1.5um EML in half-butterfly package	No replacement
E2560D35	10G 1.5um EML in half-butterfly package	No replacement
E2560D36	10G 1.5um EML in half-butterfly package	No replacement
E2560D37	10G 1.5um EML in half-butterfly package	No replacement
E2560D38	10G 1.5um EML in half-butterfly package	No replacement



<b>Current part number</b>	<b>Description</b>	<b>Recommended replacement number</b>
E2560D39	10G 1.5um EML in half-butterfly package	No replacement
E2560D40	10G 1.5um EML in half-butterfly package	No replacement
E2560D41	10G 1.5um EML in half-butterfly package	No replacement
E2560D42	10G 1.5um EML in half-butterfly package	No replacement
E2560D43	10G 1.5um EML in half-butterfly package	No replacement
E2560D44	10G 1.5um EML in half-butterfly package	No replacement
E2560D45	10G 1.5um EML in half-butterfly package	No replacement
E2560D46	10G 1.5um EML in half-butterfly package	No replacement
E2560D47	10G 1.5um EML in half-butterfly package	No replacement
E2560D48	10G 1.5um EML in half-butterfly package	No replacement
E2560D49	10G 1.5um EML in half-butterfly package	No replacement
E2560D50	10G 1.5um EML in half-butterfly package	No replacement
E2560D51	10G 1.5um EML in half-butterfly package	No replacement
E2560D52	10G 1.5um EML in half-butterfly package	No replacement
E2560D53	10G 1.5um EML in half-butterfly package	No replacement
E2560D54	10G 1.5um EML in half-butterfly package	No replacement
E2560D55	10G 1.5um EML in half-butterfly package	No replacement
E2560D56	10G 1.5um EML in half-butterfly package	No replacement
E2560D57	10G 1.5um EML in half-butterfly package	No replacement
E2560D58	10G 1.5um EML in half-butterfly package	No replacement
E2560D59	10G 1.5um EML in half-butterfly package	No replacement
E2560D60	10G 1.5um EML in half-butterfly package	No replacement
E2560G	10G 1.5um EML in half-butterfly package	No replacement
E2560G31	10G 1.5um EML in half-butterfly package	No replacement
E2560G32	10G 1.5um EML in half-butterfly package	No replacement
E2560S	10G 1.5um EML in half-butterfly package	No replacement
E2560S21	10G 1.5um EML in half-butterfly package	No replacement
E2560S22	10G 1.5um EML in half-butterfly package	No replacement
E2560S23	10G 1.5um EML in half-butterfly package	No replacement
E2560S24	10G 1.5um EML in half-butterfly package	No replacement
E2560S25	10G 1.5um EML in half-butterfly package	No replacement
E2560S26	10G 1.5um EML in half-butterfly package	No replacement
E2560S27	10G 1.5um EML in half-butterfly package	No replacement
E2560S28	10G 1.5um EML in half-butterfly package	No replacement
E2560S29	10G 1.5um EML in half-butterfly package	No replacement
E2560S30	10G 1.5um EML in half-butterfly package	No replacement
E2560S31	10G 1.5um EML in half-butterfly package	No replacement
E2560S32	10G 1.5um EML in half-butterfly package	No replacement
E2560S33	10G 1.5um EML in half-butterfly package	No replacement
E2560S34	10G 1.5um EML in half-butterfly package	No replacement

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.



<b>Current part number</b>	<b>Description</b>	<b>Recommended replacement number</b>
E2560S35	10G 1.5um EML in half-butterfly package	No replacement
E2560S36	10G 1.5um EML in half-butterfly package	No replacement
E2560S37	10G 1.5um EML in half-butterfly package	No replacement
E2560S38	10G 1.5um EML in half-butterfly package	No replacement
E2560S39	10G 1.5um EML in half-butterfly package	No replacement
E2560S40	10G 1.5um EML in half-butterfly package	No replacement
E2560S41	10G 1.5um EML in half-butterfly package	No replacement
E2560S42	10G 1.5um EML in half-butterfly package	No replacement
E2560S43	10G 1.5um EML in half-butterfly package	No replacement
E2560S44	10G 1.5um EML in half-butterfly package	No replacement
E2560S45	10G 1.5um EML in half-butterfly package	No replacement
E2560S46	10G 1.5um EML in half-butterfly package	No replacement
E2560S47	10G 1.5um EML in half-butterfly package	No replacement
E2560S48	10G 1.5um EML in half-butterfly package	No replacement
E2560S49	10G 1.5um EML in half-butterfly package	No replacement
E2560S50	10G 1.5um EML in half-butterfly package	No replacement
E2560S51	10G 1.5um EML in half-butterfly package	No replacement
E2560S52	10G 1.5um EML in half-butterfly package	No replacement
E2560S53	10G 1.5um EML in half-butterfly package	No replacement
E2560S54	10G 1.5um EML in half-butterfly package	No replacement
E2560S55	10G 1.5um EML in half-butterfly package	No replacement
E2560S56	10G 1.5um EML in half-butterfly package	No replacement
E2560S57	10G 1.5um EML in half-butterfly package	No replacement
E2560S58	10G 1.5um EML in half-butterfly package	No replacement
E2560S59	10G 1.5um EML in half-butterfly package	No replacement
E2560S60	10G 1.5um EML in half-butterfly package	No replacement

---

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.