

PRODUCT DISCONTINUATION

PD-ION-8TA5-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNI	Discontinuation	Notify Distributors and Field	9/21/2015

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The Tempcon products are being discontinued from the Inline Modular Product Family. While Phoenix Contact does not offer a direct one to one replacement, we can offer a migration path using an alternative Phoenix Contact hardware and software set. To best assist you with the alternative product set, please contact our Technical Service department with the specifics of your application.

Warranty Information:

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 10/30/2015

Last Scheduled Ship from Phoenix Contact: 4/30/2016

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

JASON HALDEMAN
 Product Marketing Lead Specialist
 (717)944-1300x3746
 jhaldeman@phoenixcon.com

Thank you,



 , Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
2861807	IB IL TEMPCON UTH-PAC		
2861771	IB IL TEMPCON RTD-PAC		