


NO: NT-094 **PRODUCT:** NT-DRT21 DeviceNet Interface
DATE: October 2015 **TYPE:** Discontinuation Notice

NT-DRT21 DeviceNet Interface for NT631/NT31 HMIs to be Discontinued; Replace with NS HMI and Ethernet Interface

Discontinuation date: August 2016

Sales of NT31C and NT631C have dropped as designers favor HMIs with updated graphics and Ethernet-based communications. The direct link to DeviceNet slave units, NT-DRT21, became unnecessary with the introduction of NS-series HMIs.

There is no recommended replacement for this unit. If the unit needs to be replaced it is recommended that the NT631C/NT31C be replaced with a NS-series HMI and either NT-Link or Ethernet communications to the controller.



Affected Parts

Product discontinuation	Recommended replacement
NT-DRT21	NS-Series HMI and either NT-Link or Ethernet

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.