

# PRODUCT CHANGE NOTIFICATION

PCN#: COPPER CABLE

20191111-1

ISSUE DATE:

20191023

IMPACTED REGIONS:

NA

EMEA

LATAM

AP

REASON FOR CHANGE:

DISCONTINUATION

OTHER

**DESCRIPTION OF CHANGE: (Not Required for discontinuation)**

As a result of global rationalization and simplification of the Panduit copper cable portfolio, we have consolidated two products into one. Both products have similar attributes and function. Please review the product notification for a list of the affected parts

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	11	11
Old product discontinuation date*	2020	1	11

**\*Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PUO6C04BL-U	PUO6C04BL-CEG
PUO6C04BL-U-S	PUO6C04BL-CEG-S