

# PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES 20210831-1

Product Group ID AND SAFETY

ISSUE DATE: 31-Aug-21

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Discontinuing thermal transfer terminal block markers

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	2	28

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(S)	Replacement Part 1	Discontinuation Date
TB05X12EWT-AB1	NO-REPLACEMENT	28-Feb-22
TB06X12EWT-AB1	NO-REPLACEMENT	28-Feb-22
TB06X08EWT-AB2	NO-REPLACEMENT	28-Feb-22
TB05X08EWT-AB2	NO-REPLACEMENT	28-Feb-22
TB08X12EWT-AB1	NO-REPLACEMENT	28-Feb-22