



PCN - 10 121re-issue

Issue Date: March 09 2011

Product Name:	HPL538, Solder plating of SFV_S series		
	62674-xx1121, 62674-1121W, 62674-xx1141		
Product Manager:	Shoichi Omote		
Subject:	Discontinuance Notification		
Distribution:	GLOBAL		
Type of Change:	Product Obsolescence		
Change Description:	Product Discontinuance		
Reason for Change:	The supply of the solder plating contact becomes impossible with the closedown of the Ishioka factory. So, solder plating products are eliminated and gold plating type is set as alternative.		
Affected Parts:	See list attached.		
Effective Date of Change:	September	30	2011
Last Time Buy Date:	September	30	2011
Last Disty Return Date:	June	30	2011
Datasheet Attached?	N/A		
Qual/Test Data Attached?	N/A		
Samples Availability Date:	September	30	2010
Available Alternatives?	Yes	Gold plating products (62674-xx1121ALF, 62674-1121WALF, 62674-xx1141ALF)	
Questions?	Contact your local FCI Representative, or		
	Shoichi Omote		
	81-3-5493-5232 / shoichi.omotefci.com		

Item Number	Effective Date	Last Buy Date	Alternate Part
62674-081121	31-Aug-11	30-Sep-11	62674-081121ALF
62674-121121	31-Aug-11	30-Sep-11	62674-121121ALF
62674-161121	31-Aug-11	30-Sep-11	62674-161121ALF
62674-201121	31-Aug-11	30-Sep-11	62674-201121ALF
62674-201121W	31-Aug-11	30-Sep-11	62674-201121WALF
62674-211121	31-Aug-11	30-Sep-11	62674-211121ALF
62674-221121ZLF	31-Aug-11	30-Sep-11	62674-221121ALF
62674-241121	31-Aug-11	30-Sep-11	62674-241121ALF
62674-241121W	31-Aug-11	30-Sep-11	62674-241121WALF
62674-241141	31-Aug-11	30-Sep-11	62674-241141ALF
62674-251121	31-Aug-11	30-Sep-11	62674-251121ALF
62674-261121	31-Aug-11	30-Sep-11	62674-261121ALF
62674-261121ZLF	31-Aug-11	30-Sep-11	62674-261121ALF
62674-301121	31-Aug-11	30-Sep-11	62674-301121ALF
62674-301121ZLF	31-Aug-11	30-Sep-11	62674-301121ALF
62674-321121	31-Aug-11	30-Sep-11	62674-321121ALF
62674-321121ZLF	31-Aug-11	30-Sep-11	62674-321121ALF
62674-331121	31-Aug-11	30-Sep-11	62674-331121ALF