

INFORMATION NOTE



N° 002/15

Change of SP-number for TLE4291E

Subject of Change: Update of SP-number for PCN 2012-115 (TLE4291E)

Products affected:	Type	SP N°	OPN	Package
	TLE4291E	SP000754260	TLE4291EXUMA1	PG-SSOP-14

Reason of Change: Align order numbers for clear identification of old and new parts for PCN 2012-115

Description of Change:	<u>Old</u>	<u>New(Update for PCN2012-115)</u>
Change of SP-number	SP000754260 OPN: TLE4291EXUMA1	SP001191330 (for PCN2012-115) OPN: TLE4291EXUMA2

Assessment: No impact on form, fit, function or reliability.

Time Schedule: 2015-03-31

Documentation: n.a.

If you have any questions, please do not hesitate to contact your local Sales office.