

PRODUCT CHANGE NOTIFICATION

Product Category COPPER PATCHCORDS 20221202-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 2-Dec-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The following parts of 24 AWG Cat6A LSZH patch cords are being discontinued. Customers have the option to replace parts with similar length parts within the product family, move to Category 6A (UTP6AL), or move to the 28AWG Dual Rated option (UTP28SP%) offering.

Parts remaining in this product family will be the following:

1-5M - in 0.5M Increments | 6-10M - in 1.0M increments | 15, 20 in the following Colors (BU, Off White, BL, GY, GR, OR, YL, RD)
 25, 30, 40, 50M will be offered in BU and Off White only

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	12	12
Old product discontinuation date*	2023	3	2

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Discontinuation Date
UTPSPL0.2MGR/NY	Compatible	UTPSPL0.5MGRY	3/2/2023
UTPSPL0.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL1MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL1.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL2MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL2.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL3MBUR/NY	No Replacement	No Replacement	3/2/2023
UTPSPL3MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL3.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL4MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL4.5MGY/NY	Compatible	UTPSPL5MGYY	3/2/2023
UTPSPL4.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL5.5MBLY	Compatible	UTPSPL6MBLY	3/2/2023
UTPSPL5.5MBUY	Compatible	UTPSPL6MBUY	3/2/2023
UTPSPL5.5MGRY	Compatible	UTPSPL6MGRY	3/2/2023
UTPSPL5.5MY	Compatible	UTPSPL6MY	3/2/2023
UTPSPL5.5MORY	Compatible	UTPSPL6MORY	3/2/2023
UTPSPL5.5MRDY	Compatible	UTPSPL6MRDY	3/2/2023
UTPSPL5.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL5.5MYLY	Compatible	UTPSPL6MYLY	3/2/2023
UTPSPL6MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL6.5MBLY	Compatible	UTPSPL7MBLY	3/2/2023
UTPSPL6.5MBUY	Compatible	UTPSPL7MBUY	3/2/2023
UTPSPL6.5MGYY	Compatible	UTPSPL7MGY/NY	3/2/2023
UTPSPL6.5MGRY	Compatible	UTPSPL7MGRY	3/2/2023
UTPSPL6.5MY	Compatible	UTPSPL7MY	3/2/2023
UTPSPL6.5MORY	Compatible	UTPSPL7MORY	3/2/2023
UTPSPL6.5MRDY	Compatible	UTPSPL7MRDY	3/2/2023
UTPSPL6.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL6.5MYLY	Compatible	UTPSPL7MYLY	3/2/2023
UTPSPL7MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL7.5MBLY	Compatible	UTPSPL8MBLY	3/2/2023
UTPSPL7.5MBUY	Compatible	UTPSPL8MBUY	3/2/2023
UTPSPL7.5MGYY	Compatible	UTPSPL10MGY/NY	3/2/2023
UTPSPL7.5MGRY	Compatible	UTPSPL8MGRY	3/2/2023
UTPSPL7.5MY	Compatible	UTPSPL8MY	3/2/2023
UTPSPL7.5MORY	Compatible	UTPSPL8MORY	3/2/2023
UTPSPL7.5MRDY	Compatible	UTPSPL8MRDY	3/2/2023
UTPSPL7.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL7.5MYLY	Compatible	UTPSPL8MYLY	3/2/2023
UTPSPL8MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL8.5MBLY	Compatible	UTPSPL9MBLY	3/2/2023
UTPSPL8.5MBUY	Compatible	UTPSPL9MBUY	3/2/2023
UTPSPL8.5MGYY	Compatible	UTPSPL10MGY/NY	3/2/2023
UTPSPL8.5MGRY	Compatible	UTPSPL9MGRY	3/2/2023
UTPSPL8.5MY	Compatible	UTPSPL9MY	3/2/2023

UTPSPL8.5MORY	Compatible	UTPSPL9MORY	3/2/2023
UTPSPL8.5MRDY	Compatible	UTPSPL9MRDY	3/2/2023
UTPSPL8.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL8.5MYLY	Compatible	UTPSPL9MYLY	3/2/2023
UTPSPL9MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL9.5MBLY	Compatible	UTPSPL10MBLY	3/2/2023
UTPSPL9.5MBUY	Compatible	UTPSPL10MBUY	3/2/2023
UTPSPL9.5MGYY	Compatible	UTPSPL10MGY/NY	3/2/2023
UTPSPL9.5MGRY	Compatible	UTPSPL10MGRY	3/2/2023
UTPSPL9.5MY	Compatible	UTPSPL10MY	3/2/2023
UTPSPL9.5MORY	Compatible	UTPSPL10MORY	3/2/2023
UTPSPL9.5MRDY	Compatible	UTPSPL10MRDY	3/2/2023
UTPSPL9.5MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL9.5MYLY	Compatible	UTPSPL10MYLY	3/2/2023
UTPSPL10MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL10.5MYLNY	Compatible	UTPSPL15MYLY	3/2/2023
UTPSPL11MBLY	Compatible	UTPSPL15MBLY	3/2/2023
UTPSPL11MBUY	Compatible	UTPSPL15MBUY	3/2/2023
UTPSPL11MGRY	Compatible	UTPSPL15MGRY	3/2/2023
UTPSPL11MY	Compatible	UTPSPL15MY	3/2/2023
UTPSPL11MORY	Compatible	UTPSPL15MORY	3/2/2023
UTPSPL11MRDY	Compatible	UTPSPL15MRDY	3/2/2023
UTPSPL11MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL11MYLY	Compatible	UTPSPL15MYLY	3/2/2023
UTPSPL12MBLY	Compatible	UTPSPL15MBLY	3/2/2023
UTPSPL12MGRY	Compatible	UTPSPL15MGRY	3/2/2023
UTPSPL12MORY	Compatible	UTPSPL15MORY	3/2/2023
UTPSPL12MRDY	Compatible	UTPSPL15MRDY	3/2/2023
UTPSPL12MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL12MYLY	Compatible	UTPSPL15MYLY	3/2/2023
UTPSPL13MBLY	Compatible	UTPSPL15MBLY	3/2/2023
UTPSPL13MBUY	Compatible	UTPSPL15MBUY	3/2/2023
UTPSPL13MGRY	Compatible	UTPSPL15MGRY	3/2/2023
UTPSPL13MY	Compatible	UTPSPL15MY	3/2/2023
UTPSPL13MORY	Compatible	UTPSPL15MORY	3/2/2023
UTPSPL13MRDY	Compatible	UTPSPL15MRDY	3/2/2023
UTPSPL13MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL13MYLY	Compatible	UTPSPL15MYLY	3/2/2023
UTPSPL14MBLY	Compatible	UTPSPL15MBLY	3/2/2023
UTPSPL14MBUY	Compatible	UTPSPL15MBUY	3/2/2023
UTPSPL14MGRY	Compatible	UTPSPL15MGRY	3/2/2023
UTPSPL14MY	Compatible	UTPSPL15MY	3/2/2023
UTPSPL14MORY	Compatible	UTPSPL15MORY	3/2/2023
UTPSPL14MRDY	Compatible	UTPSPL15MRDY	3/2/2023
UTPSPL14MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL14MYLY	Compatible	UTPSPL15MYLY	3/2/2023
UTPSPL15MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL16MBLY	Compatible	UTPSPL20MBLY	3/2/2023

UTPSPL16MBUY	Compatible	UTPSPL20MBUY	3/2/2023
UTPSPL16MGYY	Compatible	UTPSPL20MGY/NY	3/2/2023
UTPSPL16MGRY	Compatible	UTPSPL20MGRY	3/2/2023
UTPSPL16MY	Compatible	UTPSPL20MY	3/2/2023
UTPSPL16MORY	Compatible	UTPSPL20MORY	3/2/2023
UTPSPL16MRDY	Compatible	UTPSPL20MRDY	3/2/2023
UTPSPL16MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL16MYLY	Compatible	UTPSPL20MYLY	3/2/2023
UTPSPL17MBLY	Compatible	UTPSPL20MBLY	3/2/2023
UTPSPL17MBUY	Compatible	UTPSPL20MBUY	3/2/2023
UTPSPL17MGYY	Compatible	UTPSPL20MGY/NY	3/2/2023
UTPSPL17MGRY	Compatible	UTPSPL20MGRY	3/2/2023
UTPSPL17MY	Compatible	UTPSPL20MY	3/2/2023
UTPSPL17MORY	Compatible	UTPSPL20MORY	3/2/2023
UTPSPL17MRDY	Compatible	UTPSPL20MRDY	3/2/2023
UTPSPL17MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL17MYLY	Compatible	UTPSPL20MYLY	3/2/2023
UTPSPL18MBLY	Compatible	UTPSPL20MBLY	3/2/2023
UTPSPL18MBUY	Compatible	UTPSPL20MBUY	3/2/2023
UTPSPL18MGYY	Compatible	UTPSPL20MGY/NY	3/2/2023
UTPSPL18MGRY	Compatible	UTPSPL20MGRY	3/2/2023
UTPSPL18MY	Compatible	UTPSPL20MY	3/2/2023
UTPSPL18MORY	Compatible	UTPSPL20MORY	3/2/2023
UTPSPL18MRDY	Compatible	UTPSPL20MRDY	3/2/2023
UTPSPL18MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL18MYLY	Compatible	UTPSPL20MYLY	3/2/2023
UTPSPL19MBLY	Compatible	UTPSPL20MBLY	3/2/2023
UTPSPL19MBUY	Compatible	UTPSPL20MBUY	3/2/2023
UTPSPL19MGYY	Compatible	UTPSPL20MGY/NY	3/2/2023
UTPSPL19MGRY	Compatible	UTPSPL20MGRY	3/2/2023
UTPSPL19MY	Compatible	UTPSPL20MY	3/2/2023
UTPSPL19MORY	Compatible	UTPSPL20MORY	3/2/2023
UTPSPL19MRDY	Compatible	UTPSPL20MRDY	3/2/2023
UTPSPL19MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL19MYLY	Compatible	UTPSPL20MYLY	3/2/2023
UTPSPL20MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL25MBLY	Compatible	UTPSPL25MBUY	3/2/2023
UTPSPL25MGRY	Compatible	UTPSPL25MBUY	3/2/2023
UTPSPL25MORY	Compatible	UTPSPL25MBUY	3/2/2023
UTPSPL25MRDY	Compatible	UTPSPL25MBUY	3/2/2023
UTPSPL25MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL25MYLY	Compatible	UTPSPL25MBUY	3/2/2023
UTPSPL26MVL/NY	No Replacement	No Replacement	3/2/2023
UTPSPL30MBLY	Compatible	UTPSPL30MBUY	3/2/2023
UTPSPL30MGRY	Compatible	UTPSPL30MBUY	3/2/2023
UTPSPL30MORY	Compatible	UTPSPL30MBUY	3/2/2023
UTPSPL30MRDY	Compatible	UTPSPL30MBUY	3/2/2023
UTPSPL30MVLY	No Replacement	No Replacement	3/2/2023

UTPSPL30MYLY	Compatible	UTPSPL30MBUY	3/2/2023
UTPSPL35MBLY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MBUY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MGRY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MORY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MRDY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL35MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL35MYLY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL40MBLY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL40MGRY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL40MORY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL40MRDY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL40MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL40MYLY	Compatible	UTPSPL40MBUY	3/2/2023
UTPSPL45MBLY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MBUY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MGYY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MGRY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MORY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MRDY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL45MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL45MYLY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MBLY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MGYY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MGRY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MORY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MRDY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL50MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL50MYLY	Compatible	UTPSPL50MBUY	3/2/2023
UTPSPL55MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL55MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL55MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL55MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL55MY	No Replacement	No Replacement	3/2/2023
UTPSPL55MORY	No Replacement	No Replacement	3/2/2023
UTPSPL55MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL55MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL55MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL60MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL60MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL60MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL60MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL60MY	No Replacement	No Replacement	3/2/2023
UTPSPL60MORY	No Replacement	No Replacement	3/2/2023
UTPSPL60MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL60MVLY	No Replacement	No Replacement	3/2/2023

UTPSPL60MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL65MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL65MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL65MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL65MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL65MY	No Replacement	No Replacement	3/2/2023
UTPSPL65MORY	No Replacement	No Replacement	3/2/2023
UTPSPL65MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL65MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL65MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL70MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL70MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL70MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL70MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL70MY	No Replacement	No Replacement	3/2/2023
UTPSPL70MORY	No Replacement	No Replacement	3/2/2023
UTPSPL70MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL70MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL70MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL75MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL75MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL75MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL75MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL75MY	No Replacement	No Replacement	3/2/2023
UTPSPL75MORY	No Replacement	No Replacement	3/2/2023
UTPSPL75MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL75MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL75MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL80MBLY	No Replacement	No Replacement	3/2/2023
UTPSPL80MBUY	No Replacement	No Replacement	3/2/2023
UTPSPL80MGYY	No Replacement	No Replacement	3/2/2023
UTPSPL80MGRY	No Replacement	No Replacement	3/2/2023
UTPSPL80MY	No Replacement	No Replacement	3/2/2023
UTPSPL80MORY	No Replacement	No Replacement	3/2/2023
UTPSPL80MRDY	No Replacement	No Replacement	3/2/2023
UTPSPL80MVLY	No Replacement	No Replacement	3/2/2023
UTPSPL80MYLY	No Replacement	No Replacement	3/2/2023
UTPSPL2MRDF/NY	No Replacement	No Replacement	3/2/2023