



TOSHIBA AMERICA ELECTRONIC COMPONENTS INC.

To: DigiKey

October 2016

Please be informed Toshiba has announced discontinuation on the following product(s) in October 2016. Our sales records indicate you have purchased the following product(s) from Toshiba America Electronic Components in the past.

**Products**

Generic PN	TSB PN	Last Time Buy	Last Shipment	Substitution Code	Replacement PN	Reason
1SS302TE85LF	1SS302(TE85L,F)	12/31/2017	3/31/2018	1	1SS302A.LF(T	Integration of products
SSM3K301T(TE85L,F)	SSM3K301T(TE85L,F)	12/31/2017	3/31/2018	3	SSM3K324R.LF(T	Integration of products
SSM3K310T(TE85L,F)	SSM3K310T(TE85L,F)	12/31/2017	3/31/2018	3	SSM3K123TU.LF(T	Integration of products
SSM3K7002BF,LF	SSM3K7002BF,LF(T	12/31/2017	3/31/2018	1	T2N7002AK,LF(T	Chip Shrink
SSM6N7002BFU(T5L,F)	SSM6N7002BFU(T5L,F)	12/31/2017	3/31/2018	1	SSM6N7002CFU,LF(T	Chip Shrink
SSM6N7002BFU,LF	SSM6N7002BFU,LF(T	12/31/2017	3/31/2018	1	SSM6N7002CFU,LF(T	Chip Shrink
TC75W70L8X,LF	TC75W70L8X,LF(S	12/31/2017	3/31/2018	3	TC75S70L6X,LF(S	Others
TC7SZ07AFS(TPL3)	TC7SZ07AFS(TPL3)	12/31/2017	3/31/2018	1	TC7SZ07AFS,L3J(T	Others
TC7SZ34AFS,L3F	TC7SZ34AFS,L3F(T	12/31/2017	3/31/2018	1	TC7SZ34AFS,L3J(T	Others
TC7W02FUTE12LF	TC7W02FU(TE12L,F)	12/31/2017	3/31/2018	2	TC7WH02FU,LJ(CT	Others
TC7W32FKTE85LF	TC7W32FK(TE85L,F)	12/31/2017	3/31/2018	2	TC7WH32FK,LJ(CT	Others
TC7W32FUTE12LF	TC7W32FU(TE12L,F)	12/31/2017	3/31/2018	2	TC7WH32FU,LJ(CT	Others
TC7WB126FK(TE85L,F)	TC7WB126FK(TE85L,F)	12/31/2017	3/31/2018	0	TC7WB66CFK(not available yet)	Others

**Last Time Buy (LTB) Option**

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Logic Device, Discrete Business Unit  
Toshiba America Electronic Components, Inc.

=====

Substitution Level\*\*

0 = No replacement

1 =Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

4 = Other reason