



Product Change Notification

TE Connectivity

Product Change Notification: P-18-015820

PCN Date: 11-MAY-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Change of pickup location for Trutnov sourced ES2000 and ATUM parts.

Description of Changes

Pickup location of ES2000 and ATUM parts will change from TE's WCDC in Ontario, CA to PADC in Mechanicsburg, PA. To be tied to PCN P-18-015354 and P-18-015360 that stated change of manufacturing location for these parts.

Reason for Changes:

Product improvement. Parts listed in this change notice were previously manufactured at TE's facility at Menlo Park, CA. Since this facility is being closed, manufacturing has been moved to Trutnov, Czech Republic. Changing pickup location to PADC will shorten LT of Made to Order parts by 2 weeks, as shipments from Trutnov arrive on the East Coast of the US by ocean transit. New LT for PADC was already communicated on notifications about manufacturing location change.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	11-JUN-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB08994001	NO						
NB09012001	NO						
NB09304001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09524001	NO						
NB09542001	NO			"ATUM--16/4-0-STK"			
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10364001	NO						
NB10594001	NO						
NB10884001	NO						
NB11022001	NO						
NB11234001	NO						
NB11354001	NO						
NB11644001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12034001	NO						
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09542001	NO			"ATUM--16/4-0-STK"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB11022001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
NB08994001	NO						
NB09304001	NO						
NB09524001	NO						
NB09944001	NO						
NB10364001	NO						
NB10594001	NO						
NB10884001	NO						
NB11234001	NO						
NB11354001	NO						
NB11644001	NO						
NB12034001	NO						