

Product Change Notification - GBNG-16HAGS756

Date: 27 Jun 2017
Product Category: Trusted Platform Module
Notification subject: End of Life (EOL) of selected AT97SC3205T Atmel device family.
Notification text: **PCN Status:**
End of Life (EOL) notification

Microchip Parts Affected:

Please open the attachments found in the attachments field below labeled as PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:

The selected AT97SC3205T Atmel device family will be moving to End of Life (EOL) status effective today. Please review the attached parts affected list for details about replacement parts if applicable. These devices will no longer be offered after December 15, 2017.

Reason for EOL:

- No longer have manufacturing support for the CPN listed in the attachment.
- PCR data return was incorrect for 12C customers and secure field upgrade failed to modify large sections of the EE as required

Estimated Effective Dates:

Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:
Last date for bookings (LTB): September 15, 2017
Last date for shipments (LTS): December 15, 2017

Revision History:

June 27, 2017: Issued the EOL notification.

Attachment(s): [PCN_GBNG-16HAGS756_Affected CPN.pdf](#)
[PCN_GBNG-16HAGS756_Affected CPN.xlsx](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

GBNG-16HAGS756_Affected CPN - End of Life (EOL) of selected AT97SC3205T Atmel device family.

Affected Catalog Part Number (CPN)

| PCN_GBNG-16HAGS756 | | | |
|-------------------------------|-------------------------|--|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement | |
| AT97SC3205T-G3M44-00 | AT97SC3205T-G3M4C-00 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4400B | AT97SC3205T-G3M4C00B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M46-00 | AT97SC3205T-G3M4C-00 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4600B | AT97SC3205T-G3M4C00B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M44-10 | AT97SC3205T-G3M4C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4410B | AT97SC3205T-G3M4C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M46-10 | AT97SC3205T-G3M4C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4610B | AT97SC3205T-G3M4C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M44-20 | AT97SC3205T-G3M4C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4420B | AT97SC3205T-G3M4C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M46-20 | AT97SC3205T-G3M4C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-G3M4620B | AT97SC3205T-G3M4C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M44-00 | AT97SC3205T-H3M4C-00 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M4400B | AT97SC3205T-H3M4C00B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M46-00 | AT97SC3205T-H3M4C-00 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M4600B | AT97SC3205T-H3M4C00B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M44-10 | AT97SC3205T-H3M4C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |

GBNG-16HAGS756_Affected CPN - End of Life (EOL) of selected AT97SC3205T Atmel device family.

Affected Catalog Part Number (CPN)

| PCN_ GBNG-16HAGS756 | | | |
|-------------------------------|-------------------------|--|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement | |
| AT97SC3205T-H3M4410B | AT97SC3205T-H3M4C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M46-10 | AT97SC3205T-H3M4C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M4610B | AT97SC3205T-H3M4C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M44-20 | AT97SC3205T-H3M4C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M4420B | AT97SC3205T-H3M4C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M46-20 | AT97SC3205T-H3M4C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-H3M4620B | AT97SC3205T-H3M4C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A14-10 | AT97SC3205T-X3A1C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A1410B | AT97SC3205T-X3A1C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A16-10 | AT97SC3205T-X3A1C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A1610B | AT97SC3205T-X3A1C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A14-10 | AT97SC3205T-U3A1C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A1410B | AT97SC3205T-U3A1C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A16-10 | AT97SC3205T-U3A1C-10 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A1610B | AT97SC3205T-U3A1C10B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A14-20 | AT97SC3205T-X3A1C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A1420B | AT97SC3205T-X3A1C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |

GBNG-16HAGS756_Affected CPN - End of Life (EOL) of selected AT97SC3205T Atmel device family.

Affected Catalog Part Number (CPN)

| PCN_ GBNG-16HAGS756 | | | |
|-------------------------------|-------------------------|--|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement | |
| AT97SC3205T-X3A16-20 | AT97SC3205T-X3A1C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-X3A1620B | AT97SC3205T-X3A1C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A14-20 | AT97SC3205T-U3A1C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A1420B | AT97SC3205T-U3A1C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A16-20 | AT97SC3205T-U3A1C-20 | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |
| AT97SC3205T-U3A1620B | AT97SC3205T-U3A1C20B | The new CPN contains updated firmware version 1.2.42.10. | Contact Your Local Sales Office |