

# Product Change Notice



Date: 5/17/13	Distribution List:
Overview	Change to lead wires
Reason for change:	Change required to meet CCC approval requirements
Affected Part No:	3500, 3600, 3650, 3800, 4600TZ, 4890N, 8500DP, 8500N, 8500N-308, 8500NU, 8500TV, 8500VW, 8550N, 8550VW, 8800N, 8830N, 8830VW, 8850N, 8880N, RL90-18/00, RL90-18/50, 8500N-14 4600ZW-11
Design Change Detail:	All fan models listed currently come with 18AWG wire. Fans will be change to used 22 AWG wire with insulation diameter of 2.4mm.
Effective Date:	Q3:2013
Agency:	No impact on UL approvals for fan
Samples:	On request only
Pricing:	No impact
Customer Approval:	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> other (see comment section)
Attachments:	A list of part numbers shipped to our distributors over the past 12 months effected by the change.

Comments:	<p>Customer Approval will be determined on a case by case basis depending on feedback from our Distributors' sales team.</p> <p>Please contact the ebm-papst Regional Distribution Sales person or the local ebm-papst sales person as needed.</p>