



# AKM Semiconductor, Inc.

## End of Life Notice

Document ID : AKMSWF150730A  
 Product affected : Listed below  
 Date of notification : 07/30/2015

Last order date: 10/30/2015  
 Last shipment date: 05/31/2016

AKM will discontinue below listed products due to market demands.

Product affected :

AK4564VQ	AK8998W	AK6440AF	AK6508CS	AK93C45CU	AK93C65CF	AK8980	AK8977A
<b>AK5371VQ*</b>	AK6003AV	AK6440AM	AK6508DTS	AK93C55AF	AK93C65CM	HW300A	AK8977
AK2563D	AK6416AL	AK6440BH	AK6514CN	AK93C55AV	AK93C65CU	AK8962C	
AK2563E	AK6416AM	AK6440BL	AK6921FBB	AK93C55BH	AK93C75AV	AK8970N	
AK2563D	AK6416CH	AK6480AF	AK93C10AF	AK93C55BL	AK93C85AM	AK8970	
AK2563E	AK6417AL	AK6480AM	AK93C41AV	AK93C55CU	AK93C95AF	AK8971N	
AK8996	AK6417AM	AK6480BH	AK93C45AF	AK93C65AF	AK9813BF	<b>AK8973*</b>	
AK8996W	AK6417CM	AK6480BL	AK93C45AV	AK93C65AV	AK9822M	AK8976A	
AK8998D	AK6420AF	AK6481CM	AK93C45BH	AK93C65BH	AK9824M	AK8976K	
AK8998	AK6420AM	AK6506CTU	AK93C45BL	AK93C65BL	AK8783	AK8976A	

Suggested replacement products (for parts indicated in **BOLD\***) :

Affected Part Number	Suggested Replacement Part
AK5371VQ	AK5371A <a href="http://www.akm.com/akm/en/file/datasheet/AK5371AVQ.pdf">http://www.akm.com/akm/en/file/datasheet/AK5371AVQ.pdf</a>
AK8973 (QFN-16 package)	AK8963N <a href="http://www.akm.com/akm/en/file/datasheet/AK8963.pdf">http://www.akm.com/akm/en/file/datasheet/AK8963.pdf</a>

AKM will consider this notice fully noticed and approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice.

Ryo Inoue  
 Sales Administration Manager  
 AKM Semiconductor, Inc.  
 1731 Technology Drive, Suite 500  
 San Jose, CA 95110