

Product Change Notice

Issue Date: 17-August-2021

Change Description:

Adding Substrate Supplier for Enduro/56334 and ARAD+/88660

Parts Affected:

BCM56132B1IFSBLG
BCM56132B1KFSBLG
BCM56134B1IFSBLG
BCM56134B1KFSBLG
BCM56146MB1KFSBLG
BCM56146PB1KFSBLG
BCM56149MB1KFSBLG
BCM56230B1IFSBLG
BCM56230B1KFSBLG
BCM56231B1IFSBLG
BCM56320B1IFSBLG
BCM56320B1KFSBLG
BCM56321B1IFSBLG
BCM56321B1KFSBLG
BCM56321LB1KFSBLG
BCM56331B1IFSBLG
BCM56331B1KFSBLG
BCM56333B1IFSBLG
BCM56333B1KFSBLG
BCM56334B1IFSBLG
BCM56334B1KFSBLG
BCM56334LB1IFSBLG
BCM56334LB1KFSBLG
BCM56338B1IFSBLG
BCM56338B1KFSBLG
BCM88360A0IFSBLG
BCM88360A0KFSBLG
BCM88361A0IFSBLG
BCM88361A0KFSBLG
BCM88363LA0KFSBG
BCM88460A0IFSBLG
BCM88460A0KFSBLG
BCM88461A0IFSBLG
BCM88560A0KFSBLG
BCM88561LA0KFSBG
BCM88562A0KFSBLG
BCM88660A0IFSBLG
BCM88660A0KFSBLG



BCM88661A0KFSBLG
BCM88664A0KFSBLG
BCM88664LA0KFSBG

Description and Extent of Change:

Adding an additional substrate supplier

Reasons for Change:

Provide manufacturing flexibility and supply continuity

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification has been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:

Product shipments using this change will begin after 11/18/2021. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

Qualification Data:

Qualification Data has been generated and will be provided upon request

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.