

---

## Product Change Notification (PCN)

---

Issue Date: **11/16/2020**  
Modification/Revision Date: **11/16/2020**

Change Notification: **PCN-US-20201101**

Description of changes: **Obsolete**

Date of change and Implementation: **Change 11/16/2020**

Key Characteristics of Change: **Obsolete**

Products Affected:

**Part numbers listed below**

Reason for Change: **No longer offered**

Response: **No response to this notification is required.**

---

## Product Change Notification (PCN)

---

**Issue Date:** 11/16/2020  
**Modification/Revision Date:** 11/16/2020

Part Number	Replacement	Part Number	Replacement
A-TB000-AE00	no replacement	A-TB350-TS04EF	no replacement
A-TB000-AF00	no replacement	A-TB350-TS05B	no replacement
A-TB100-H202	no replacement	A-TB350-TS05BF	no replacement
A-TB100-H203	no replacement	A-TB350-TS24BF	no replacement
A-TB100-H205	no replacement	A-TB350-TS24EF	no replacement
A-TB100-H206	no replacement	A-TB350-YO14SB	no replacement
A-TB250-OQ06CV	no replacement	A-TB350-YO15SB	no replacement
A-TB250-OQ07CH	no replacement	A-TB350-YQ10L	no replacement
A-TB250-OQ07CV	no replacement	A-TB350-YQ11L	no replacement
A-TB250-OQ08CH	no replacement	A-TB381-HP14	no replacement
A-TB250-OQ08CV	no replacement	A-TB381-HP23	no replacement
A-TB250-OQ09CH	no replacement	A-TB381-HW03	no replacement
A-TB250-OQ10CH	no replacement	A-TB381-VK14F	no replacement
A-TB250-OQ10CV	no replacement	A-TB381-VK18F	no replacement
A-TB250-OQ11CH	no replacement	A-TB381-VK22F	no replacement
A-TB250-OQ12CV	no replacement	A-TB500-TP10	no replacement
A-TB250-OQ13CH	no replacement	A-TB500-TP12	no replacement
A-TB250-OQ17CH	no replacement	A-TB500-TP13	no replacement
A-TB250-OQ19CH	no replacement	A-TB500-VJ02V	no replacement
A-TB250-OQ20CV	no replacement	A-TB508-TJ04DF	no replacement
A-TB250-OQ21CH	no replacement	A-TB508-TJ05DF	no replacement
A-TB250-VL18V	no replacement	A-TB508-TJ10DF	no replacement
A-TB250-VL20V	no replacement	A-TB508-TJ20DF	no replacement
A-TB350-OQ04HF	no replacement	A-TB508-TP10	no replacement
A-TB350-OQ04VF	no replacement	A-TB508-TP12	no replacement

## Product Change Notification (PCN)

Issue Date: **11/16/2020**  
Modification/Revision Date: **11/16/2020**

Part Number	Replacement	Part Number	Replacement
A-TB508-TP13	no replacement	A-TB254-HA18H	no replacement
A-TB508-TS09E	no replacement	A-TB254-HA24H	no replacement
A-TB508-V704H	no replacement	A-TB381-VL06V	no replacement
A-TB508-V704V	no replacement	A-TB381-VL18V	no replacement
A-TB508-V705H	no replacement	A-TB381-VL20H	no replacement
A-TB508-V705HF	no replacement	A-TB381-VL20V	no replacement
A-TB508-V705V	no replacement	A-TB381-VM14	no replacement
A-TB508-V705VF	no replacement	A-TB381-VM14F	no replacement
A-TB508-V706V	no replacement	A-TB381-VM15	no replacement
A-TB508-V708V	no replacement	A-TB381-VM15F	no replacement
A-TB508-V714H	no replacement	A-TB381-VM17	no replacement
A-TB508-V714V	no replacement	A-TB381-VM17F	no replacement
A-TB508-V716H	no replacement	A-TB381-VM18	no replacement
A-TB508-V716V	no replacement	A-TB381-VM19	no replacement
A-TB750-H212	no replacement	A-TB381-VM20	no replacement
A-TB750-OQ07OV	no replacement	A-TB381-VM24	no replacement
A-TB750-OQ09OH	no replacement	A-TB381-VO04VF	no replacement
A-TB762-TJ07DF	no replacement	A-TB381-VO06VF	no replacement
A-TB762-TJ08DF	no replacement		
A-TB762-TJ09DF	no replacement		
A-TB762-VB07F	no replacement		
A-TB762-VC05SC	no replacement		
A-TB762-VC07SC	no replacement		
A-TB952-T703	no replacement		
A-TB150-EI02	no replacement		