

PRODUCT CHANGE NOTIFICATION

Product Category STRONGHOLD 20210422-1

Product Group STRONGHOLD

ISSUE DATE: 22-Apr-21

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The Stronghold Pigtail Parts are being discontinued. Please review Product Change Notification for further details.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2021	7	22

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type
SGPL10-9S-L	No Replacement
SGPL12-7S-L	No Replacement
SGPL12-8S-L	No Replacement
SGPL12-10S-L	No Replacement
SGPL12-12S-L	No Replacement
SGPL14-8S-L	No Replacement
SGPS12-8SRF-L	No Replacement
SGPS12-8SRT-L	No Replacement
SGPS12-8FT-L	No Replacement
SGPSL12-8SFT-Q	No Replacement
SGPSS12-8SFT-Q	No Replacement
SGPSS12-8SFF-Q	No Replacement
SGPSSL12-8S-Q	No Replacement
SGPSSS12-8S-Q	No Replacement
SGPS12-8FT-L10	No Replacement
SGPS12-8FT-L20	No Replacement
SGPS12-8FT-L2	No Replacement
GSC10-32-38-C	No Replacement
GSH10-32-38-C	No Replacement