

+ CORPORATE HEADQUARTERS

707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USA

p: (800) 346-3119
f: (815) 433-5109

+ EUROPEAN HEADQUARTERS

Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Ireland

p: + 353 91 792444
f: + 353 91 792445

+ CELLULAR PRODUCTS GROUP

Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republic

p: +420 465 521 020
f: +420 464 647 299

Product EOL Notice

June 29, 2018

Model	Description
BB-856-14012	iMcV-FiberLinX-II, TX/FX-MM1300-SC
BB-856-14016	iMcV-FiberLinX-II, TX/FX-SM1310/PLUS-SC
BB-856-14018	iMcV-FiberLinX-II, TX/FX-SM1310/LONG-SC
BB-856-14047	iMcV-FiberLinX-II, TX/SSFx -SM-SC(1310XT/1550RV)
BB-856-14048	iMcV-FiberLinX-II, TX/SSFx-SM-SC(1550XT/1310RV)
BB-856-14058	iMcV-FiberLinX-II, TX/FX-CWDM-SM1430-SC
BB-856-14059	iMcV-FiberLinX-II, TX/FX-CWDM-SM1450-SC
BB-856-14205	iMcV-Giga-FiberLinX-III, TX/SX- MM850-SC
BB-856-14224	iMcV-GigaFiberLinX-III, TX/SSLX-SM1310/PL-SC(1310xmt/1550rcv)
BB-856-14225	iMcV-GigaFiberLinX-III, TX/SSLX-SM1550/PL-SC(1550xmt/1310rcv)

This is the end-of-life announcement for the products listed above. Last time buy orders will be accepted until September 30, 2018.

Product Migration Path:

Current	Replacement
BB-856-14012	BB-856-14500, BB-808-38102(LC connector)
BB-856-14016	BB-856-14500, BB-808-38104(LC connector)
BB-856-14018	BB-856-14500, BB-808-38105(SM1550, LC connector)
BB-856-14047	BB-856-14500, BB-808-38121
BB-856-14048	BB-856-14500, BB-808-38122
BB-856-14058	No replacement
BB-856-14059	No replacement
BB-856-14205	BB-856-14201, BB-808-38201(LC connector)
BB-856-14224	BB-856-14201, BB-808-38221
BB-856-14225	BB-856-14201, BB-808-38222

Contact B+B SmartWorx for availability. Full product documentation is available on our website www.advantech-bb.com , or via our support staff: support@advantech-bb.com

Thank You,



Stan Simmons | Product Sales Manager