

Issue Date: March 19,2020

Dear Valued Customer,

This notice is to inform you of a product change affecting selected items that you have purchased from Littelfuse.

Description of the Change:

The manufacturing locations for plastic components associated with Part Number: 883-083 & 883-084, are being insourced from an outside injection molding supplier to a Littelfuse injection molding facility.

Part Numbers Affected:

| Component | Part Number |
|-----------|-------------|
| 883-083 | PDM21001LXM |
| 883-083 | PDM21002LXM |
| 883-083 | PDM21004LXM |
| 883-083 | PDM21005LXM |
| 883-083 | PDM71001ZXM |
| 883-083 | PDM71002ZXM |
| 883-083 | PDM71003ZXM |
| 883-083 | PDM71004ZXM |
| 883-083 | PDM71006ZXM |
| 883-083 | PDM71007ZXM |
| 883-083 | PDM71008ZXM |
| 883-083 | PDM71009ZXM |

| Component | Part Number |
|-----------|-------------|
| 883-084 | PDM31001ZXM |
| 883-084 | PDM31004ZXM |
| 883-084 | PDM31002ZXM |

Reason for Change:

The above parts are being insourced to strengthen our supply chain and increase our responsiveness to demand.

Effective Date of the Change:

The transition will happen over the course of Q2, 2020 with a tentative completion date of: 5/27/20



Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

What You Need to Do:

New quality and PPAP documentation will be prepared upon completion of the transfer and available upon request.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Joe Plazyk

Global Product Manager
Commercial Vehicle Products
Littelfuse, Inc.