



# Product Change Notification

## TE Connectivity

Product Change Notification: P-17-014878

PCN Date: 26-SEP-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
 CII Midrange Manufacturing Location Change

Description of Changes  
 Dear Valued Customer, This letter is notification of an upcoming manufacturing location change involving TE Connectivity, CII brand 5 to 50 amp midrange electromechanical and time delay relays. This is a change in production site only and does not affect the design or form-fit-function of the product in any way. Over the course of the next several months, TE will be migrating its standard catalog and QPL midrange product lines to our Cochin, India production facility. This facility currently manufactures our high volume T0-5/Minigridd and Crystal Can relays (M39016 types).  
 Other attachments:  
[Midrange Manufacturing Location Change](#)  
[Manufacturing Location Change Questions](#)

Reason for Changes:  
 Manufacturing location change

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-JAN-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1617761-3</a>	NO			"FCB-405-BZ4"			
<a href="#">7-1617760-7</a>	NO			"FCB-405-0617M"			
<a href="#">8-1617760-0</a>	NO			"FCB-405-0620M"			
<a href="#">8-1617760-1</a>	NO			"FCB-405-0621M"			
<a href="#">8-1617760-2</a>	NO			"FCB-405-0622L"			
<a href="#">8-1617760-6</a>	NO			"FCB-405-0625M"			
<a href="#">8-1617783-2</a>	NO			"FCB-405-BY4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1617761-3</a>	NO			"FCB-405-BZ4"			
<a href="#">7-1617760-7</a>	NO			"FCB-405-0617M"			
<a href="#">8-1617760-0</a>	NO			"FCB-405-0620M"			
<a href="#">8-1617760-1</a>	NO			"FCB-405-0621M"			
<a href="#">8-1617760-2</a>	NO			"FCB-405-0622L"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">8-1617760-6</a>	NO			"FCB-405-0625M"			
<a href="#">8-1617783-2</a>	NO			"FCB-405-BY4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">7-1617760-7</a>	NO			"FCB-405-0617M"			
<a href="#">8-1617760-0</a>	NO			"FCB-405-0620M"			
<a href="#">8-1617760-6</a>	NO			"FCB-405-0625M"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1617761-3</a>	NO			"FCB-405-BZ4"			
<a href="#">8-1617760-1</a>	NO			"FCB-405-0621M"			
<a href="#">8-1617760-2</a>	NO			"FCB-405-0622L"			
<a href="#">8-1617783-2</a>	NO			"FCB-405-BY4"			