

## End of Life Notice

To : Digi-Key Corporation

Document ID : AKMSLF160428C\_Rev.2  
 Product affected : Listed below  
 Date of notification : 9/13/2016 (Revised on Sep.13 \*EM1711 removed from the list)  
 Type of change : N/A  
 Reason for change : Vendor's decision  
 Last order date : Aug.31, 2016  
 Last shipment date : Sep.30, 2017

### Description :

AKM will discontinue below listed products due to market demand situation.

### Product affected :

Table 1/2

Part number	Part number	Part number	Part number
AK2117BJW	AK2510B	AK4255ET	AK4682AEQ
AK2130MFW	AK2511A	AK4322VF	AK4682EQ
AK2141FFW	AK2570P	AK4324VF	AK4686EQ
AK2143FW	AK2923T	AK4341ET	AK4687EQ
AK2151DS	AK2923UA	AK4368EG	AK4690EG
AK2170BBW	AK2923U	AK4388VT	AK4702EQ
AK2170BJW	AK2924T	AK4392EQ	AK4702VQ
AK2170BW	AK2927U	AK4397EQ	AK4705VQ
AK2170JW	AK2928T	AK4421AET	AK4707EQ
AK2170PDABMW	AK2943N	AK4421ET	AK4709EQ
AK2170PDBFW	AK4116VN	AK4424AET	AK5330VM
AK2170PDBJW	AK4124VF	AK4424ET	AK5351VF
AK2175ABW	AK4125XF	AK4429ET	AK5352VF
AK2175BLW	AK4126XQ	<del>AK4430ET</del> *Removed	AK5354VT
AK2175GWT	AK4140VF	AK4534VQ	AK5366VQ
AK2175PDGWT	AK4160EN	AK4543VQ	AK5367EF
AK2175TJW	AK4161EN	AK4554VL	AK5380VT
AK2182AJW	AK4187ZEN	AK4568AER	AK5385AVF
AK2182BJW	AK4203ET	AK4586VQ	AK5385AVS
AK2186ENAJMW	AK4250VT	AK4664VQ	AK5401AVQ
AK2210	AK4250VU	AK4666VQ	AK5404VQ
AK2358F	AK4255AET	AK4673EG	AK5406XQ

Table 2/2

Part number	Part number	Part number	Part number
AK5483	AK8180C	AK8928SA	EM301
AK6508DU	AK8180D	AK8929B	EQ8441
AK7601VQ	AK8181A	AK8929M	EW6671
AK7730VT	AK8408	AK8929S	HG0111
AK7740VT	AK8415VF	AK8932	HG0112
AK7770EQ	AK8418	AK8981AH	HG0113
AK7811ABB	AK8419AVQ	AK9216-VS	HG0114
AK7811BB	AK8419BVQ	AK93C55CL	HG0115
AK7831BB	AK8434VQ	AK93C65CUA	HG106R
AK7835S5	AK8440VQ	AK9813BYFRP	HW109A
AK7837ABB	AK8441VQ	AP1601	HW209A
AK8117L	AK8445VN	EM0683	MS0080
<del>AK8130A</del> *Removed	AK8454W	EM0711	MW010
AK8131C	AK8533P	EM0712	MW011
AK8131S	AK8812	EM0771	MW012
AK8132A	AK8856VN	EM0781	MW013
AK8150CU	AK8927D	EM0791	MW020
AK8170BU	AK8927LB	EM1661	MW310
AK8180A	AK8928C	<del>EM1711</del> *Removed	
AK8180B	AK8928	EM300	

### **Suggested Alternative Part**

Affected product	Suggested replacement product (functional equivalent parts)	
AK4116VF	AK4117VF	<a href="http://www.akm.com/akm/en/file/datasheet/AK4117VF.pdf">http://www.akm.com/akm/en/file/datasheet/AK4117VF.pdf</a>
AK5380VT	AK5381VT	<a href="http://www.akm.com/akm/en/file/datasheet/AK5381VT.pdf">http://www.akm.com/akm/en/file/datasheet/AK5381VT.pdf</a>
AK5385AVF	AK5385BVF	<a href="http://www.akm.com/akm/en/file/datasheet/AK5385BVF.pdf">http://www.akm.com/akm/en/file/datasheet/AK5385BVF.pdf</a>
AK5385AVS	AK5385BVS	<a href="http://www.akm.com/akm/en/file/datasheet/AK5385BVS.pdf">http://www.akm.com/akm/en/file/datasheet/AK5385BVS.pdf</a>

AKM will consider this notice fully noticed and approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice.

Ryo Inoue  
Sales Administration Manager  
AKM Semiconductor, Inc.  
1731 Technology Drive, Suite 500  
San Jose, CA 95110